

Meeting Minutes Transmittal - Approved

Unit Managers Meeting 304 CONCRETION FACILITY FEDERAL BUILDING, RM 784-A Richland, Washington

Meeting Held November 22, 1994 From 10:00 am to 11:30 am

Via video teleconference

The undersigned indicate by their signatures that these meeting minutes reflect the actual occurrences of the above dated Unit Managers Meeting.

Date: Mattlin, Unit Manager, RL	
Not Present Date: Daniel L. Duncan, RCRA Program Manager, EPA R	egion 10
Date: Satt & Molhning Scott E. McKinney, Unit Manager, Washington S	tate Department
304 Concretion Facility, WHC Concurrer	ıce

te: 6/1/95

Fred A. Ruck III, Contractor Representative, WHC

Date: 1/1/55

Ivan L. Metcalf, Contractor Representative, WHC

Purpose: Discuss Permitting Process

Meeting Minutes are attached. The minutes are comprised of the following:

Attachment 1 - Agenda

Attachment 2 - Summary of Discussion and Commitments/Agreements

Attachment 3 - Attendance List

Attachment 4 - Action Items

Attachment 5 - Analytical Results, Drum of dirt for electrical trench

excavations

Attachment 6 - Radiation Survey Results, electrical trench excavations

Attachment 7 - Ecology Guidance on concrete sampling

Attachment 8 - Ecology Comments of October 13, 1994, with

responses.

Attachment 9 - Phase I Sampling and Analysis Plan for the 304 Concretion

Facility Closure Activities

Unit Managers Meeting 304 CONCRETION FACILITY FEDERAL BUILDING, RM 784-A Richland, Washington

Meeting Held November 22, 1994 From 10:00 am to 11:30 am

Via video teleconference

Agenda

- 1. Approval of Past UMM Minutes
- 2. Status Action Items
 - 9-23-94:1
 9-23-94:3
 10-13-94:1
 10-13-94:2
 10-13-94:3
 10-13-94:4

 Letter on NODs (Ecology)
 Answer tour questions (WHC)
 Report on disposition of the decon rags (WHC)
 Confirm that perchloroethylene is the same compound as tetrachloroethylene (WHC)
 Ethyl acetate (WHC)
 Guidance on sampling concrete for VOA (Ecololgy)
- Status Closure Activities
 - Status of Ecology's Review of Closure Plan Revision 2
 - Status of Decontamination/Sampling Activities
 - Status of Sampling Analysis Plan
- 4. New Business
- Set Next Meeting Date

Unit Managers Meeting 304 CONCRETION FACILITY FEDERAL BUILDING, RM 784-A Richland, Washington

Meeting Held November 22, 1994 From 10:00 am to 11:30 am

Via video teleconference

Summary of Discussion and Commitments/Agreements

1. Approval of Past UMM Minutes

The August 25, 1994, September 23, 1994, and October 13, 1994 meeting minutes have not been reviewed or approved.

2. Status Action Items

9-23-94:1 Prepare a letter closing out previous NODs and transmitting this last NOD comment. Ecology (S. E. McKinney)

Ecology has not been able to prepare the letter by the due date of November 22, 1994. See "Status of Ecology's Review of Closure Plan Revision 2" for a complete discussion of this issues.

This action remains open.

9-23-94:3 Provide answers to Ecology's questions from the 304 Facility tour. WHC (J. G. Adler)

In response to Ecology's questions on the dirt removed from the electrical trench excavations and containerized for radiological concerns: WHC (J. A. Remaize) reported that the dirt has also been analyzed for heavy metals and none were detected. The analytical results requested by Ecology are attached (attachment 5). This implies that there may be less heavy metal contamination in the soil at the 304 Facility then originally feared.

In response to Ecology's request for any radiation survey results from the electrical trench excavations: WHC (J. L. Wright) reported that the survey results for the trench within the 304 Facility boundary came back as negative. That is, all survey results were at the detection levels of the instruments (below 5,000 DPM). The survey results are attached (attachment 6).

This action item is now closed.

10-13-94:1 Report on the disposition of the decon rags. WHC (J. L. Wright)

and the second second

WHC (J. L. Wright) reported that the decontamination rags will be disposed of according the designation used for the material (mostly semi-consolidated cement) removed from the sump. This is consistent with the procedures outlined in Environmental Investigations and Site Characterization Manual WHC-CM-7-7 procedures for investigation derived waste. The resulting designation is expected to be for a radioactive mixed waste.

Ecology (S. E. McKinney) asked what was the total amount of waste from the decontamination activities. WHC responded that there are three 55-gal drums: one drum of rags and assorted clothing from the decontamination effort, one drum of clothes from the sump clean-out, and one drum of debris (dirt and concrete) from the sump clean-out.

This action item is now closed.

10-13-94:2 Confirm that perchloroethylene is the same compound as tetrachloroethylene. WHC (J. G. Adler)

WHC (J. G. Adler) reported that a check of several references confirmed that both perchloroethylene and tetrachloroethylene are the same compound, H²C:CH², Chemical Abstract Service (CAS) Number 126-18-4. For revision 3 of the closure plan, the Table 7-2 will be revised to drop perchloroethylene and add a foot note indicating that they are the same chemical compound.

This action item is now closed.

10-13-94:3 Try and identify why ethyl acetate was left off and if it should be added to the SAP. WHC (J. G. Adler)

WHC (J. G. Adler) reported that a review of the DQO meeting minutes suggest that the group failed to identify ethyl acetate as a U-listed waste. Ethyl acetate has been added back into revision 1 of the SAP.

This action item is now closed.

10-13-94:4 Provide comments on the SAP relative to Ecology's guidance on sampling concrete for volatile organics. Ecology (S.E. McKinney)

Ecology (S. E. McKinney) provided guidance to WHC on November 2, 1992 to reduce the number of concrete organic samples in the sampling plan. A copy of the guidance is attached (attachment 7).

This action item is now closed.

3. Status Closure Activities

- Status of Ecology's Review of Closure Plan Revision 2

Ecology (S. E. McKinney) stated that the close-out letter had not been started yet. Ecology expressed concern that when Ecology's planned priority work through December had been set-up, Ecology was not able to include the 304 Facility close-out letter as part of that work-load.

- Status of Decontamination/Sampling Activities

WHC (J. G. Adler) stated that there have been no changes in the status of the decontamination or sampling activities at the 304 Facility since the last meeting. The decontamination is complete and sampling will be scheduled to start when the Sampling and Analysis Plan is approved by Ecology.

- Status of Sampling Analysis Plan

WHC (J. G. Adler) reported that the Ecology comments from the last UMM had been addressed. A handout with the Ecology comments and WHC responses in attached (attachment 8)

A copy of the final draft sampling and analysis plan (SAP) for the 304 Facility had been sent via express mail to Ecology. This copy is identical to the revision 1 of the SAP (attachment 9) that was approved for public release short before this Unit Manager's Meeting. A copy of the final revision 1 of the SAP will be sent to Ecology via next-day mail.

RL/WHC request verbal approval of the SAP, followed by written approval, from Ecology as soon as possible.

There is one change from the draft red-line copy provide to Ecology earlier in the month. In the analysis for methyl ethyl ketone, the analytical method has been changed from SW-846 Method 8015 to Method 8240. The primary driver is that the WHC 222-S Laboratory does not have a 8015 procedure in place while they have an 8240.

Start of sampling depends upon 2 things: Ecology's approval of the SAP and a modification to the existing laboratory contract. The modification is needed to add SW-846 Method 8260. The exact date that this will be completed is not known at this time, but is expected to occur during the week of December 5th or December 12th. Provided that Ecology approval is granted and that the contract modification is in place, sampling could start as early as the week of December 5th. However, the week of December 12th is considered more likely.

Ecology stated that if sampling is occurring during the tentatively scheduled UMM during December 13, 1994, then Ecology would like to observe the sampling. WHC reported that an Ecology visit would not be

a problem and that RL/WHC would keep Ecology informed on when sampling will occur.

4. New Business

Use of Debris Rule for Closure

Ecology (S. E. McKinney) and RL (E. M. Mattlin)/WHC (J. G. Adler/F. A. Ruck III) briefly discussed the use of the 'Debris Rule' for use in the closure of facilities like the 304 Concretion Facility. All parties consider that there is great potential for use of the debris rule. However, several issue still need to be resolved or investigates. Some these issue include cost of disposal of mixed waste, air permitting concerns, funding, and appropriate equipment. WHC will be continuing its examination of the debris rule and is working to determine when and where it could be applied.

5. Set Next Meeting Date

The next Unit Manager's Meeting has be tentatively scheduled for December 13, 1994 in Richland, WA.

Unit Managers Meeting 304 CONCRETION FACILITY FEDERAL BUILDING, RM 784-A Richland, Washington

Meeting Held November 22, 1994 From 10:00 am to 11:30 am

Via video teleconference

Attendance List

Name To Adh- Lathy Knox	Organization シロモ WHC	Phone # 376 251
Lathy Knox		
· · · · · · · · · · · · · · · · · · ·	V * '\C	372-3596
JOHN A REMAILE	WHC	372-1462
Jaiet Uright	WIK	
ELLEN MATTUN	DOE-RL	376-2385
	,	
Via Vida		
Scott Mc Kinny	Graleyy	200 407 7146
Navet Dright EHEN MATTLIN VIA U. d Scott Mc Viana,	WIX DOE-RL	376-2385

Unit Managers Meeting 304 CONCRETION FACILITY FEDERAL BUILDING, RM 784-A Richland, Washington

Meeting Held November 22, 1994 From 10:00 am to 11:30 am

Via video teleconference

Action Items

Action Item	<u>ı #</u>	<u>Description</u>
9-23-94:1	OPEN	Prepare a letter closing out previous NODs and transmitting this last NOD comment. Ecology (S. E. McKinney)
9-23-94:3	CLOSED 11/22/94	Provide answers to Ecology's questions from the 304 Facility tour. WHC (J. G. Adler)
10-13-94:1	CLOSED 11/22/94	Report on the disposition of the decon rags. WHC (J. L. Wright)
10-13-94:2	CLOSED 11/22/94	Confirm that perchloroethylene is the same compound as tetrachloroethylene. WHC (J. G. Adler)
10-13-94:3	CLOSED 11/22/94	Try and identify why ethyl acetate was left off and if it should be added to the SAP. Due date Friday, 10/21/94. WHC (J. G. Adler)
10-13-94:4	CLOSED 11/22/94	Provide comments on the SAP relative to Ecology's guidance on sampling concrete for volatile organics. Due date Friday, 10/21/94. Ecology (S. E. McKinney)

Unit Managers Meeting 303-K STORAGE FACILITY FEDERAL BUILDING, RM 784-A Richland, Washington

Meeting Held November 22, 1994 From 10:00 am to 11:30 am

Via video teleconference

TITLE - Analytical Results, Drum of dirt for electrical trench excavations



18939 120th Avenue N.F., Suita 101 - Uodred, WA 98017-9509 (705) 461-9700 + FAX 465-2992 Itsel 11115 Micropromy, Julie D . Spolvana, WA 00F08 4778 (600) 924-2700 - FAX 924-9290 9405 S.W. Nimbus Aversin + Reswerton, OR 97908-7132 (503) 613 9200 + FAX 644-2202

Battelle Pacific NW Laboratories 🤻 P.O. Box 999, M/S P8-45 Richland, WA 99352 Attention: Sam Juracich

NORTH ORDER

Sample Descript: 303-A TRENCH

Client Project D: Kaiser Engineers Hanford

Analysis Method: EPA 1311/6010/7000 Sample Number: 410-1406

Oct 20, 1994 Sampled: Oct 25, 1994 Received: TCLP Exi: Oct 24, 1984

Analyzed: Oct 26-27, 1994 Oct 27, 1994 Reported:

TCLP Extraction Metals

Analyte	Regulatory Level mg/L (ppm)		- Reporting Limit mg/L (ppm)	-	Sample Results mg/L (ppm)
Arsenic	. 5.0		0.20		N.D.
Bartum	-1-		1.0		N.D.
Cadmium		.441448444444	0.0050		N.D.
Chromium	···	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	0.010		N.D.
Load	·· <u>-</u>	.1	0.10		N.D.
Mercury			0.0010		N.D.
Salenium		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	0.15		N.D.
Silver			0.020	,,10,	N.D.

Analytes reported as N.D. were not detected above the stated Reporting Umit.

NORTH CREEK ANALYTICAL Inc.

Matthew T. Essig Project Manager

4101488.BHW <1>

Unit Managers Meeting 303-K STORAGE FACILITY FEDERAL BUILDING, RM 784-A Richland, Washington

Meeting Held November 22, 1994 From 10:00 am to 11:30 am

Via video teleconference

TITLE - Radiation Survey Results, electrical trench excavations

1				Date		ŀ	ime		Survey Nur	mber 165	5981	F (Page o	f
				5	23-1	<u>4</u> F	rom <u>Q 7 5</u>	/ <u>S</u> to <u>/J/3</u>				I I	Í	Cy.
	R	ADIATION SU	RVEY REPORT	Bldg	N	1		300		Room	NA			
Descr	ption	of Job			<u> </u>	<u>'</u>		RWP No.	, ,	Location	N. a	f 30	3	
[e b K1	continer or eres de Mande	ued coverin Lissing in D al 303 & Ination enco	s Po Inde Sou	ryrov thai ered	Ci I 3 I to	1 y	Check if appro Perso CAM/		checked, do no lation m	t place unre 	lated informa	tion on this re ation Level Wo urvey" release	
			<u> </u>	Mete		Ĭ	T	DOSE RATE			CONT	ΑΜΙΝΑΊΙΟΝ Ι	EVELS	
Item No	F R		vork Performed, Radiation — and Measurements	Deflec		C F	beta (no	n gamma (pen)	neutron	Direct	(dpm)	S	mear 100 cm ²	
','	(1)			W/O	W/C		pen) mrac	l/hr mR/hr	mrem/hr	beta	alpha	beta (d/m)	alpha (d/m)	mrad/hr
	ļ	1101004-85	1 tramoved				1			1000	120			
7		T .	surveyed			/	1			4 1000	120			
1			10/ Surveyed	/ -		1/	1			< 1000	120			
3		0 · L S 2 2 2 1	10 / 3 oct 10 chem			1								
	╁—	-		-			1							
	ļ						 			_	·			
- 1	} 					-	 		<u></u>					l
! !			· ·											
	-						1					L <u> </u>		
! Ch	ect to	n personnel dose ra	ne [] Continued on supple	mentalic	aport form									
i nove	ised ised		∐ G-M-Pancake ☐ PA	.M							Respira	atory Protecti	on Worn	
Seni	al No	(5)	1960 1208 2	$\frac{1}{12}$	7 /						Supplied A	ır		
				ED PERSC	ONNEL DOS	RATES					Filter			
	Р	hase of Work	Based on Measureme	nt(s)	Ave	rage Do	se Rate	Limit Ap	oplying 	_	اما	- N 3		
-								WBP	S F		Other			
-								WBP	\$ E		None			
					/			₩ВР	S E	<u> </u>	x - 3			
RPT	PT Exposure			w	l /ork Locatio	n Code	NA		med Spaler Crah					
			/P requirements for this work			d a pre-		for this work? 译字es	Rev	viewed By	<u> </u>		Date	

			Date 15'- 2	5-94	Time From	080	0 _{To} 151	Survey Nu	16!	5986	FC J	Page o	7
RAL	DIATION SU	JRVEY REPORT	Bldg 303	A , 3	04		Area 3 <i>00</i>	7	Room	NA			
Description of		<i>(*</i>		,			RWP No.	1	Location	Bal	en Bu?	100	c
Let	lueen 3	of Power Cr 03A + 304. List was have closylamination	Job wa	s shut	down	1	Check if appro	opriate. When onnel Contamir (Radiation Alar olish Dose Rate	checked, do no nation im	ot place unre		ation on this re ation Level Wo urvey" Release	cord
P Item E	Description of V	Vork Performed, Radiation	Meter Deflection	Dist C	F		DOSE RATE	1			I NOITANIMAT	···	
Mo R	Controls	and Measurements	W/O W/C	- DISC C	beta	a (non mrad/h	gamma (pen) ir mR/hr	neutron mrem/hr	Direct	(dpm) alpha	heta (d/m)	imear 100 cm? alpha (d/m)	mradihi
	Asaba /	1 surveyed			,/	-		- W	4000	500	<1000	120	
!!1	1	of back hale			4				4 1000	4 20	1000	120	
1 1 1		Broom Surveyed	7		7-		-		1000	420	1		
1 1	Bed of dun				4	· · · · ·			4 1000	120	4 1000	120	
ifi		macl surveyed			4				- 1000	< 20			
1 1 1		who temp	<u> </u>		Z -								
i i i		ossetup	(0.5 4.5	F	1/2.	. 5	4,5						
					7								
1 Charletory	inixonnelidose ra	te [] Continued on supple	mental report	form									
Instrument(s) Used	M CP	図 G MiPancake 図 Pi	λM				/ 0			Respir	atory Protecti	on Worn	
Serial No (s)	6641	1539 2	961							Supplied A			•
		ESTIMAT	ED PERSONNE	L DOSE RAT	ES					Filter			•
Phase	se of Work	Based on Measureme	ent(s)	Average	Dose Rate		Limit Ap			Other	A second	•	
							WBP	5 E		_	· · · · · · · · · · · · · · · · · · ·		
				_/			WBP	\$ E		None			
				 -			WBP	S E	- -	000			
RP1 Exposure	MA		Work I	ocation Coc	le V	7		Sigi PR I	ned Sp	7/4			
	ase or reduce RW Yes — Explain on	Pirequirements for this work reverse side	? Did yo	u attend a p	re-job meet	ing tor	this work?	1	newed By			Date	

 	Wes Wes	tinghouse	Da	\	Time				Survey	Number		F.C)	01 Z
	Han	ford Company		119194	From	730	To	<u> 530</u>			91 <u>27</u>	15	Page	of —
RAI	DIATION SU	JRVEY REPOF	эт	31dg. 3713	303		Area 3	00		Room	N/	<u> </u>		
Description of Job				7 19 7	RWP No. R-045 Location Check if appropriate. When checked, do not place unrelated information						nation on this	record.		
	7.	69 3036	i Li H	10-2P	-0718			Personi CAM/R	nel Contamir adiation Ala sh Dose Rate	nation rm)] [High Radia Topecial S Property R	ition Level Wi urvey" elease	
					<u> </u>	<u> </u>			on/Contamin	ation Incident		RAM Ship		
P Item E	Description of V	Vork Performed, Rad		eter ection Dist.	C.F. be	ata (non	DOSE		neutron	Direc	t (dpm)	AMINATION S	mear 100 cm	,2
No. R (1)	Controls,	and Measurements			,	mrad/hr)	1 -	* 1	mrøm/hr		alpha	beta (d/m)		
7	dirt ho	3713	11/2	MA NA	N/4 N	<u> </u>	NI	4	N/A	3000	470	Na	NIA	NA
2 3	6/50 Ktop	64 30 3A				1		,	<u> </u>	4004	120			1
3	Person	18450	2							10	FB			
	`									NA	NIA			
		7//									f			
		×						<u></u>		_ _		<u> </u>		
						+	+\	_		++-				
1 Check to	or personnel dose	rete Continues	on supplemen	tal report form				1			_ i	- 1 1 		
Instrument(s		CF./() G M/Pancake	2 PAM 7	K 27/1		回、					Respira	atory Protection	on Worn	
Serial No.(s		1964 1346	2406	7.5	38					su	oplied Air			1
		EST	IMATED PERS	ONNEL DOSE	RATES					- ☐ Filt	<u> </u>	4.4		ė
Pha	se of Work	Based on Mea	surement(s)	Avera	ge Dose Rate	е		mit App	lying					
`							WBP	S	E	_	er			
							WBP	S .	<u>E</u>	E No	None /			
DOT F	110		· · · · · · · · · · · · · · · · · · ·	 	n Code		WBP	5	E Sig	ned	-0115	1921/1	7	
nr i Exposu	Honory and The F	The second second second		~ · · · · · ·					PR	No. Zo	20 M	P/ 120	67-	5/1
		WP requirements for n on reverse side.	this work?	Did you attend	a pre-job π ∏ N/A				Rø Ĺ	viewed By	5	Mer	9/8/	94

RADIATION SURVEY REPORT (cont.)	Survey Number N.D. 179127 F.C. Page of
	N= 1/912/ 1/98 - "-
Finished diaginally 3713, Moves	
pièces of blacktop, MSS+ 2 9090 had up t	o 400 c/m direct on them
DIAGRAMS OR SKETCHES 37/3 S.C.P.	300A A BOLL
ADDITIONAL REPORTS COMPLETED Log No. Radiological Problem Report Skin Contamination Survey Personnel Effects Contamination Report Radiation Survey Report	Onsite Radioactive Shipment Offsite Radioactive Shipment Routine Radioactive Shipment Sample Counter Log

Marehausa	Date	 ð		Т	ime			Survey N	lumber		F.C.		
Westinghouse Hanford Company	17	-2	1-9	14 F	rom 15/5	To <u>/</u>	546	2	Nº 17	9148	尺	Page /	of L
	1					Area			Room	1		-	
RADIATION SURVEY REPORT	Be	her	d 3	303	-/<		300	ر 					
Description of Job		2	,			RWP No.	لمسار		Locat	ion Septe	ul 303	t-RCA	۲
Resummen day Dite		رريسه(12.	ind		Check	if approp	priate. When	checked, do	not place un	related infor	nation on this	record.
303.16 Alpeane	1	30	n.	166-8	/		Personi	nel Contamina	ation			tion Level Wo	rk
,		_				i =	_	adiation Alarr			Zi≺Special S		
WHC-17-0718 3.1.	1					ــــــــــــــــــــــــــــــــــــــ	-	sh Dose Rates on/Contamina		_	☐ Property R ☐ RAM Shipi		
						DOSE		on/Contamina	Hon melesh		AMINATION		
Item P Description of Work Performed, Radiation	Met Defied		Dist.	C.F.	beta (non		a (pen)	neutron	Dire	ct (dpm)		meer 100 cm ²	
No. R Controls, and Measurements	W/O	W/C			pen) mrad/h	1 -	R/hr	mrem/hr	beta	alpha	beta (d/m)	alpha (d/m)	mrad/hr
1 lendrok det pieter			7 ⁷⁾						520	1 2500			<u> </u>
					1								
													·
	>												ļ
				$\langle -$					<u> </u>				ļ <u>.</u>
				\mapsto									
	1		L								1		1
1. Check for personnel dose rate	lemente	al repo	ort for	m.					·				
instrument(s) Used CP G-M/Pancake PAM	ı	(]		— 		- 0 -			Respira	tory Protection	on Worn	
Serial No.(s) 090/375 29	101									pplied Air			
ESTIMATED		NNEL	DOSE	RATES	 }				1				
Phase of Work Based on Measurement	(s)		Aver	age Dos	se Rate	L	imit Appl	lying	Fil	ter		1 1 12 - 1 2	t
//4						WBP	s	E	Ot	her	. Her .		
	1				7	WBP	s	E	J √J No	nne.			
					/	WBP	s	E		,			
RPT Exposure		L Vork L	ocatio	on Code				Sign	1 ed <i>L.F.M.</i>	1/12/2	Willett	1,50	
()					NA		<u>-</u>		10.540	West !			·
Did you increase or reduce RWP requirements for this work	<7 D	Did you	atte		-job meeting (F +4.	ewed By	28571	rle	Date	,
No Yes Explain on reverse side.				ĘŻ	N/A No	Ye	s		<u>. I. MIL</u>			8/8/	194

jugar a state of

RADIATION SURVEY REPORT (cont.)	Survey Number No. 179148 F.C. Page Q of 2
Further Descriptions, Data, and Comment 21 Chief the alit pells - and replicated Banner to print any one falling Whole a DSI to Supervisor of my	
stand point. BS CF = 10% CF = 7%	
DIAGRAMS OR SKETCHES	
Skin Contamination Survey Offs Personnel Effects Contamination Report Rout	Log No. Log No. Log No. Log No. Log No. Log No. Log No.

												_ r	
Westin Westin	ghouse d Company	Da		2.,	Time From 0 7 3	60 Td 6	6 T	Survey Nu	^{mber} √0 179	167	F.C.	Page /	of f
RADIATION SUR			<u> 72-77</u> Bldg. 3273 ₂			Area 30		<u> </u>	Room	2//	12		
Description of Job				<u> </u>	/1	RWP No.	R . 0	1 : e=	Locatio	n /)	///	\overline{Q}	
Diegn	ng (a) 37	1/3									related inform	ation on this	record.
Diggin Reduce S	TO A to	under	Carno	und				Contaminat				tion Level Wo	
Padroacti	1)) - 7	Laria /	ARE	ú		1 =		ation Alarm			∰ "Special St		
made RCA by 3	UIA to a	SEN L	VIta-	Ib-	07/83/			Dose Rates Contaminat	on Incident	_	Property Ro		
P Item E Description of Wor		M	eter			DOSE R	ATE				AMINATION		
No. R Controls, an	rk Performed, Had d Measurements	Deff		st. C.F.	beta (non	1 -		neutron mrem/hr	Direct	(dpm) alpha	beta (d/m)	near 100 cm ² alpha (d/m)	mrad/hr
(1)	- > , -,	\\\/\n	 -	lo Pyt	$\int n/a$	N	10	ry la	41000	120	×1000	× 20	rula.
1 \ dirt @3		1, 1, 1, 1				1	`	1 × 14	1500	ن د خ	1500	620	
of No	331-		+++						10/2	N/A	12/4	n/A	
											1		
	TV/												
				1									
	-//				1								
		7,1	1	·		7			<u> </u>	$\perp \vee \perp$	W		/i/
Check for personnel dose re	te Continue	on supplemen	ntal report	form.					· · · · · · · · · · · · · · · · · · ·				
l Osed — (-)	G-M/Pancake	□ РАМ								Respira	itory Protection	on Worn	
Serial No.(s)	18.7	2.843			,		L	<u> </u>	Sup	plied Air			
	T	IMATED PERS	1			T			Filte	or	, e		
Phase of Work	Based on Mea	surement(s)	A	verage D	lose Rate		it Applyir		Oth				
				->-		WBP	S	E					
			<u> </u>			WBP	3	E			11 12		
· ··					· · · · · · · · · · · · · · · · · · ·	WBP	S	E Sign		<u> </u>	Helip		.
RPT Exposure	and the second s		Work Loc	ation Co				PR N	o. Lo	Tex 30	11/2	5- 6732	ــلــ
Did you increase or reduce RW		this work?	Did you a		pre-job meeting		7		wed By	<u> </u>	10	Date	
No Yes Explain o	on reverse side.		l	{	□n/a □n	lo 🖾 Yes							

RADIATION SURVEY REPORT (cont.)	Survey Number Nº 179167	F.C. Page 3 - of 7
Further Descriptions, Data, and Comment 18 columns SCA IN South and 64 3213 to		
Applieded R.C. F. (a) 303 A to 9 SCA because of	contamination of 12	Sucim found
N		
DIAGRAMS OR SKETCHES	\mathcal{N}	
17713 - Heriergrand Sign.	$G_{0,3A}$ $\begin{bmatrix} x_{A} \\ y \\ y \end{bmatrix}$ $\begin{bmatrix} x_{A} \\ y \\ y \end{bmatrix}$	THE CONTRACTOR OF THE PARTY.
ADDITIONAL REPORTS COMPLETED Log No.	Į.	Log No.
Radiological Problem Report Skin Contamination Survey Personnel Effects Contamination Report	Pusite Radioactive Shipment Offsite Radioactive Shipment Outine Radioactive Shipment ample Counter Log	

Survey Number

RADIATION SURVEY	REPORT (cont.)	Survey Number Nº 179208	F.C. Page O of
Further Descriptions, Data, and Comment A MSM-CO A COMMENT COMM	digging hold (e) 303A building, North Side		-
DIAGRAMS OR SKETCHES			
Those S.			
ADDITIONAL REPORTS COMPLETED	Log No.		Log No.
Radiological Problem Report	Offs	te Radioactive Shipment ite Radioactive Shipment ine Radioactive Shipment ple Counter Log	

West West	inghouse	Dat			Time				Survey No	ımber		F.C.		
Hanfe	ord Company	8	- 5-	94 1	From 08	800) 	500	<u> </u>	Nº 179	211	T.K.	Page /	of 2
RADIATION SU	RVEY REPORT	В	Bldg.			F	30C)			Room				
Description of Job				•		F	300 (4) RWP No. 74 Location N. 303 K							
Covera Ligging	ge of had	ise - H	r C	3. 1				Personn CAM/Ra Establish	riate. When on the contamina diation Alarn to Dose Rates in/Contaminat	tion 1		_	elease	
Item F Description of Wo	ork Performed, Radiation	Met	. 1		ļ		DOSE R	ATE			· · · · · · ————	LEVELS		
h	ind Measurements	Defied W/O		t. C.F.	beta (r pen) mra		gamma mR/i		neutron airem/hr	Direct	(dpm) alpha	Sr beta (d/m)	mear 100 cm ² alpha (d/m)	nu ad/hr
				17							4 500	Deta (d) (d)	Capatra (Capatra)	
1 VECT Su					<u> </u>					1	< 500			
	1 Surveyed									-	<500	< 1000	2 270	_
3 Water spia	<u>ye.ian</u>			1-7	-					- 5000	J20	-1000	<u> </u>	
	and the second s													Y
	era				 -									
				1										
Check for personnel dose re	ate Continued on sup	plementa	al report fo	orm.	<i>V</i>		J			1	<u>, </u>	ll		
Instrument(e)									2000		Respirat	tery Protection	on Worn	
Serial No.(s)		106								Supp	F + A.			
	ESTIMATED			E RATES	 S			L			pilea Air			
Phase of Work	Based on Measureme	nt(s)	Ave	rage Dos	age Dose Rate Limit Applying Lifter		r							
	11/1					WBP S E		E	Other None					
		7			\top			E						
				WBP S E										
RPT Exposure	<u> </u>	, w	Vork Locat	ion Code	-/	7			PR No	v. 6	イフノム		bush	_
Did you increase or reduce RWI		k? D	Did you attend a pre-job meeting				for this work?					Smil.	Date 8/8/	1911

RADIATION SURVEY REPORT (cont.)	Survey Number No 179233 F.C. Page of 2
Further Descriptions, Data, and Comment	
124 4 3 501 59 MD183	1. had will go to 2005 /abs 19til-
Surveyed Spil piles.	
	<u> </u>
DIAGRAMS OR SKETCHES	
ADDITIONAL REPORTS COMPLETED	
Log No.	Log No.
Rediological Problem Report	Onsite Radioactive Shipment
Skin Contamination Survey	Offsite Radioactive Shipment
Personnel Effects Contamination Report	Routine Radioactive Shipment
Rediction Survey Report	Sample Counter Log

	Wes	tinghouse	Date		Time		Survey N	umber		F.C.	1	·····
		ford Company	8-2	9-94	From 0800	7 To 1515	_	Nº 179	292	S	Page	of 2
	RADIATION S	JRVEY REPORT		Betwe	en 03-A	Area 300	ı	Room	N	A		
Descrip	ption of Job	······						Locatio	n C.	e Pesc	L	
	Coverage	e of Power	Co+	y a s	nd	Check if appropr			ot place un	related inform	nation on this	record.
	Kaiser po	between bui	1dings	ey re	moved reper-	Personni CAM/Ra Establish	el Contamina	tion 1	[] [] []		ation Level Wo eurvey" Telease	
Item	P Description of V	Vork Performed, Radiation	Meter			DOSE RATE			CONT	AMINATION	LEVELS	···
No.	- 1	and Measurements	Deflection W/O W/C	Dist. C.F.	beta (non pen) mrad/i	1 " '	neutron mrem/hr	ļ	Direct (dpm) Smear 100			
		1 11	W/O W/C		peny mady			beta	alpha _	beta (d/m)	alpha (d/m)	mrad/hr
		shalf surveyed						< 5000				
3		i below a suhalt						2 5000				
	rersonn	el, surveyed						4 5000				
					 							
					 							
												
1. Che	ck for personnel dose		lemental repo	ort form.								
Use Serial N	11 1 00	G-M/Pancake PAM							Respira	tory Protection	on Worn	
Serial N	Vo.(s)				/			☐ Supp	lied Air			
ļ <u>.</u>		ESTIMATED	PERSONNEL	DOSE RATE	S			 Filter				
	Phase of Work	Based on Measurement	(s)	Average Do	se Rate	Limit Applyi	ng				. :	
		N				WBP S	E	Othe	·			
			4	/		WBP S	E	None				
		/				WBP / S	E					
RPT Exp	posure //	 4	Work L	ocation Code	4		Signe PR No	d SIE	lever	<i>6 A</i> 7	14	
Did you	increase or reduce RW	/P requirements for this work	Did you	attend a pri	7 e-job meeting f	or this work?		wed By	rlen	bush	Date	
[Z	Yes Explain				N/A □No			,	" Z	,		

RADIATION SURVEY REPORT (cont.)	Survey Number N. 179292 F.C. Page 2 of 1
Further Descriptions, Data, and Comment	
DIAGRAMS OR SKETCHES	
\sim \sim \sim	
/ A	
	Y
ADDITIONAL REPORTS COMPLETED	·
Łog No.	Log No.
Radiological Problem Report	Onsite Radioactive Shipment
Skin Contamination Survey	Offsite Radioactive Shipment
/	Routine Radioactive Shipment
Personnel Effects Contamination Report	
Radiation Survey Report	Sample Counter Log

Survey Number

Did you attend a pre-job meeting for this work?

□N/A ☑No □Yes

9-9-94 From 0730 To 1315

Bldg. Area

Date

Westinghouse Hanford Company

RADIATION SURVEY REPORT

Did you increase or reduce RWP requirements for this work?

Yes Explain on reverse side.

Description of Job

Survey Number

300

Personnel Contamination

Radiation/Contamination Incident

CAM/Radiation Alarm

Establish Dose Rates

Nº 179323

RWP No. MA Location Between Bldgs.

Check if appropriate. When checked, do not place unrelated information on this record.

of Z

Page

High Radiation Level Work

"Special Survey"

Property Release

RAM Shipment

Reviewed By Date

Date

Westinghouse Hanford Company

Survey Number

Nº 179330

RADIATION SURVEY REPORT (cont.)	Survey Number NO 179330 F.C.
Further Descriptions, Data, and Comment	
attached to atclephone pole. Atouto	I that may be some kind of plute
attached to atclephone pole Attouto	and what lety it and old talephone
tools, Had 300 c/m on it. Reman entaged	contracted and paggret than bur proper
de wife /	. 0 /
)
DIAGRAMS OF SYSTEMS	
DIAGRAMS OR SKETCHES	
	Miloumation child
ADDITIONAL REPORTS COMPLETED Log No.	Log No.
	On the Delta of the Chinasana
Radiological Problem Report	Onsite Radioactive Shipment Offsite Radioactive Shipment
Skin Contamination Survey	Routine Radioactive Shipment
Personnel Effects Contamination Report	Semple Counter Log
Rediation Survey Report	dumple counter sog

Westinghouse	Date		Tim				Survey Nu			F.C.	_			
Westinghouse Hanford Company	9-2	0-99	Froi	m <i>Q801</i>	2то /_	5/5	<u> </u>	<u>10 179</u>	358		Page	of 2		
RADIATION SURVEY REPORT	Bidg.	Bldg.			300	2		Room	Room					
Description of Job		۸ ۵			RWP No. M/A Location North of 303-17									
Coverage of gerson	ne.lo	اسي	جير	5,	Check if appropriate. When checked, do not place unrelated information on this record.									
in underground KM Lot North of 303	A _ in	Ua	can	1.1	Personnel Contamination High Radiation Level Work CAM/Radiation Alarm "Special Survey"									
lot North of 303	-K				1		iation Alarm Dose Rates			Special St ☐ Property R				
WHC 0718 Appen.	<u> </u>	3.1					/Contaminat	ion Incident		RAM Shipi				
P	Mater	T			DOSE RA	ATE		1	CONT	AMINATION	LEVELS			
Item E Description of Work Performed, Radiation No. R Controls, and Measurements	Deflection	Dist.	C.F.	beta (non	gamma	pen)	neutron	Direct	(dpm)	Sı	near 100 cm²			
(1)	w/o w/o			pen) mrad/h	nr) mR/t	ır	mrem/hr	beta	alpha	beta (d/m)	alpha (d/m)	mrad/hr		
1 Survey of dirt removed														
from trench									4500					
2 Personne/Surveyed				~				< 5000	< 500					
	<u> </u>													
				_	1									
			$\prec \downarrow$						<u> </u>					
Check for personnel dose rate	olennental rep	ort form	1.											
Instrument(s) CP G-M/Pancake PAI	и		/						Respira	tory Protectio	on Worn			
1505	96							Пол	plied Air					
ESTIMATED		DOSE F	RATES	I,										
Phase of Work Based on Measuremer	it(s)	Averag	je Dose	Rate	Lim	it Applyii	ng	Filte	r	over 1949.	•เกษา	EV.		
	//				WBP	S	7 E	Oth	er	W. Ow	REMITOR VIEW			
	A	/			WBP S E None									
					WBP	S	E							
RPT Exposure	Work	Location	Code	Á			Signe PR N	-	alento 14	rah				
Did you increase or reduce RWP requirements for this wor	k? Did yo	u attend	La pre jo □ N,		for this work? Yes		Revie	wed By	11 23	ml-	Data 10/5/96			
											in Same	15. als - 50î		

A STATE OF THE STA

Date

Westinghouse

Survey Number

F.C.

2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1
	200
	1.5-5/
•	5

-	
	#

Survey Number

Wostin	ghouse	Date	Date Time				Surv	ey Numb	oer		F.C.			
	d Company	9-3	26-9	From <u>Q</u> &	00	To 1500	2	N	179	380		Page /	of 2	
RADIATION SUF	OVEN BEDORT	Bldg.				Area			Room					
	TVET NEFUNT		VA		_	300 NA								
Description of Job								RWP No. R-045 Location Lot N. of 3707-G						
Coverage	at constru	retion	2n_			Check if appropriate. When checked, do not place unrelated information on this record.								
personnel	of constru	in /	of	north	-	Personnel Contamination High Radiation Level Work CAM/Radiation Alarm Properties Proper								
of 370	7-6				-		Radiation ish Dose (_	Property Re			
WHC.	-0718 Appe	n 1-	3./		_	Radiati			Incident		RAM Shipn	nent	_	
P 5	1.5.7	Meter				DOSE RATE	,			CONT	AMINATION			
No. R Controls, an	k Performed, Radiation d Measurements	Deflection		C.F. beta (r		gamma (pen) mR/hr	neuti	-	Direct beta	(dpm) alpha	Sn beta (d/m)	near 100 cm²	mrad/h	
(1)		W/O W/6		penymia		1131731	71,1011			аџла	Deta (t//II/	приа (оли)		
	surveyed								< 5000					
2 Tools sure	exed								= 5000					
- Lashaue	154 1- Pick								- 50W					
		ļ								·				
_							ļ							
				\mathcal{A}			-				·			
Check for personnel dose rat							L		1					
Instrument(s)	G-M/Pancake PAI			. [0	·					Respira	tory Protection	n Worn		
0304	931	vi _									·			
Serial No.(s)	18/2 ESTIMATED	PERSONNE	I DOSE P	ATES					Supp				1	
Phase of Work	Based on Measuremer					Limit App	olying		Filter		i esentia.		. (
	~		Average Dose Rate			WBP S			Othe	r	1111.01			
		A				WBP S		 :	None					
		·	-/-			WBP S E			(L) NORE	3				
RPT Exposure		Work	Location (Code N/				I	SJ-Ele	nera	7 35,	erlen.	bush	
1/A		A PR No. 647/4												
	You increase or reduce RWP requirements for this work? No							Reviewe	od By 	11 20	222/1	Date	lan	
LIVO LIVES EXPINION	Yes Explain on reverse side.										114/	(42.4.	7 4	

Did you attend a pre-job meeting for this work?

9-27-44 From <u>0800</u> To <u>1505</u> Bldg. Area

300

RWP No. N/A

Personnel Contamination

Radiation/Contamination Incident

CAM/Radiation Alarm

Establish Dose Rates

Date

Moe denstruction continued dieging

the trench between these 2 bldgs. in

303-A 4304

Westinghouse Hanford Company

RADIATION SURVEY REPORT

Did you increase or reduce RWP requirements for this work?

「Yos Explain on reverse side

Description of Job

Survey Number

Nº 179389 Room

Check if appropriate. When checked, do not place unrelated information on this record.

F.C.

Location Between 303-A + 304

High Radiation Level Work

"Special Survey"

Property Release

RAM Shipment

Date

Survey Number

22217:21 312:52	DEDOOT 4		Survey Number		F.C.	- 4 . 1
RADIATION SURVEY	REPORT (cont.)		Nº	179419	R	Page 2 of 2
Further Descriptions, Data, and Comment						
19 ha. auch. 100 chmc	3>					
- Sang Ville						
						
				·····		
DIAGRAMS OR SKETCHES						
						•
					100	į
						`
ADDITIONAL REPORTS COMPLETED						MORNIN
	Log No.				Log No.	ARE OF THE
Rediological Problem Report		Onsite	Radioactive Shipmer	nt		
Skin Contamination Survey			Redioactive Shipme			
			e Radioactive Shipme			
Personnel Effects Contemination Report _				71N		7
Radiation Survey Report		Sample	e Counter Log	. <u>.</u>		
	(

								· · · · · · · · · · · · · · · · · · ·			T.C			F.C.			
(W	Westin	ghouse -	 pr - 24,84	Dat (1)			i	ime	5 -	1015	Survey N		 24.2 3 .a		Page /	of 2	
	Hantor	d Company		- 60	0 - 6	- 7	9 1	rom Die	10 <u>4</u>	(16.6 .).	нючэн <u>Ү</u>	Room	14-2-(Z-11)				
RADIATI	ON SUR	RVEY REPOF	₹T						1				Joseph	<u>संच् बाख्र टिटाक</u>	scri _o tions <u>De</u>	officer Da	
Description of Job	.			130)3-H	a	ig A	ile		3 <i>0</i> 0							
1	11	-4.	/	-44	11/	a 7	4-	+ A.	RWP No. R-045 Location 303 A - 303 /c yard								
Surney	11/1/	ing tre	ICA		06	$\frac{u}{\theta}$	ae	careing	Check if appropriate. When checked, do not place unrelated information on this record. Personnel Contamination — High Radiation Level Work								
a loud of	loud of dist from the dig site @						(a) =	303A	1	_			-	- -		rk	
10 a 50	Aa	rea		<u> </u>					CAM/Radiation Alarm "Special Survey" Establish Dose Rates Property Release								
172200	ine	2 sul	nay-		WHI	= £	P-01	18 - 3.1			on/Contaminat			RAM Shipi			
P	·····		- 4/ - 	Me	ter		1		DOSE	RATE	- المعلقات من معادر والمعلقات المعلقات		ะเกา	AMINATION			
· · · · · · • · · · · · · · · · ·		rk Performed, Rad d Measurements	iation	Defle		Dist.	C.F.	beta (non	1 -	nar (pen)-	neutron		t (dpm)		mear 400 cm ²	T	
(1)				W/O	W/C		-	pen) mrad/ł	iti mi	R/hr	mrem/hr	beta	alpha	13.7	alpha (d/m)	mrad/hr	
1 Dum	p Vice	Sum	rj.			<u></u>	//	1			. —	K55	2500	21.E.	220		
Bed	tire,	1 of			-					<u></u>			wi. 741 4 5 at . 45	541 241 241	อา ยะ สด 3	MA SULABI	
2 1200	n. n.e.2	in coming			-	\bigcirc	1	<i></i>		-		21/5	< <u>20</u> 0				
		<i></i>				,		<u> </u>		-				ļ		ļ	
										····				<u> </u>			
		······									 			ļ			
								1				<u> </u>					
1 Check for person	nel dose rai	te Continued	on supp	iement	tal repo	ort for	m.				•						
Instrument(s)			⊠ PAM		ĺ,	<u></u>		F1		- 13			Respira	itory Protection	on Worn		
 		015	-			 -											
Serial No.(s)	!	330	IMATED		NNEL	DOS	FRATE	S		_L		[_]Տար	plied Air				
Phase of Wo		Based on Mea	· · · · · · · · · · · · · · · · · · ·		T			se Rate	t	Limit App	lying	Filte			TO MALE STORY		
<u></u>					 				WBP	. S bı	gal E	Oth			CERCHAN CO		
nA.								}	WBP	5		None none in the property of the state of th					
			J. 1700	111.50	<u> </u>	Hdn.		/				Later Manager Hard Hard Hard Hard Hard Hard Hard Har					
			121.	<u> </u>	Work Location Code					Signed I 772 Least 100 april 100 apr					abi8		
RPT Exposure		•	ar kyl k			ocati	он соа	е Л А -	-				ا ١١١٥٥ ويانون	and kans	stru-1		
حت Did you increase or	reduce RWf	P requirements for	this wor	k7 ·	Did ya	រ ១៥៤		e job meeting			Bevi	ewed By	Record	yar agit re alic	n.: Date		
No Tyes Explain on reverse side.							o 🗌 Ye	8S	<i>Ht</i>	Miller	288 m		14/10/	94			

RADIATION SURVEY REPORT (cont.)	Survey Number No. 179422 F.C. Page 4 of 3
Further Descriptions, Data, and Comment	1,0,122
The dist from 303A dig site is a	suspect & li placed
in on SCH & Will be taken lave of &	ates - The Lent up
Concred u/ plastic (/2 and more plaste	i will arine to finish
che solt	ν
DIAGRAMS OR SKETCHES	
ADDITIONAL REPORTS COMPLETED Log No.	Log No.
	site Radioactive Shipment
Skin Contamination Survey Off	site Radioactive Shipment
Personnel Effects Contamination Report Rou	utine Redioactive Shipment
Rediation Survey Report San	mple Counter Log
	<u> </u>

the second of the

(382) Westingho	ICO	Date	e		Т	ime	·		Survey N	umber		F.C.			
Hanford Co			10	7 9.	√ F	rom <u>0%00</u>	<u> То _</u>	600		Nº 179	433	R	Page (of Z	
	V DECORT	8	ldg.				Area			Room					
RADIATION SURVE	Y REPORT						300								
Description of Job							RWP No.	R-	045	Location	1 NORT	4 of 30	, 4	•	
COUERAGE	OF DIG SITE						Check			checked, do n				record.	
								Person	nel Contamina	ition		High Radia	tion Level Wo	ırk	
			-				I ==		adiation Alarn			"Special S	*		
	718 7RE. 3.	1.)	R 6	: v 9	$\sqrt{3}$	P. NEUD			sh Dose Rates			Property R			
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	_		, ,		· · · · · · · · · · · · · · · · · · ·	<u> </u>		on/Contamina	tion Incident		RAM Shipi			
Item E Description of Work Pe	rformed, Radiation	Met Deflec	i i	Dist.	C.F.		DOSE RATE			Direct		AMINATION	LEVELS mear 100 cm²	,	
No. R Controls, and Me	asurements	L	W/C	Dist.	C.F.	beta (non pen) mrad/h	, -	a (pen) :/hr	neutron mrem/hr	beta	olpha	beta (d/m)		mrad/hi	
					7					470	و ۲				
1 Dist Remove	2									۷ ک	 €∡	45	(ک		
2 Dung Truck										4 D	٦ - ٧	4.2	< i)		
3 BACK HOE		·		<u> </u>						< D	۷ کا	45	48		
4 E QUIPMENT										4.2	43				
5 PERSONNEL										4D					
La WORK AREA										- Z D	~ <u>D</u>		·		
						·								<u> </u>	
		1	11												
1. Check for personnel dose rate	Continued on sup	plement	al repor	rt form	n.	· · · · · · · · · · · · · · · · · · ·				Τ					
Used CP / G-	M/Pancake APA	м]		1						Respira	tory Protection	on Worn		
Serial No.(s) / (91	338 20	137								□ Supp	lied Air				
	ESTIMATED		NNEL (DOSE	RATES	5			· · · · · · · · · · · · · · · · · · ·			. •	may St.	· {	
Phase of Work	Based on Measureme	nt(s)		Avera	ge Dos	e Rate	Li	mit Appl	lying	Filter		His Ohio	Mark S.	ر خراهان	
/			/			/	WBP	S	E	Othe	r				
*/ _k	"/A		w/A				WBP S E			₩ None	₩ None				
					-		WBP	S	E	c. w. wi	<u>LDMAN</u>	}			
RPT Exposure /		v	Nork Lo	ocation	n Code		<u></u>		Sign	ed	``				
P										10 (c)	٠ ٥	75837			
Did you increase or reduce RWP requirements for this work? Did you attend a pre-job meeting No Yes Explain on reverse side.			for this wor		1	ewed By	- 1	' ₁	Date						

RADIATION SURVEY REPORT (cont.)	Survey Number	179433	F.C.	Page _ 2 of 2
Further Descriptions, Data, and Comment	0.21			
- SCA WAS REDUCED AFTER SU - BACK HOE WAS RELEASED FROM	•			
- NO PROBLEMS ENCOUNTERED				
	· · · · · · · · · · · · · · · · · · ·			
DIAGRAMS OR SKETCHES				<u> </u>
INSTRUMENTATION The α correction factor for the PAM is 7 The β correction factor for the EGM/F:11 is 10 DEFINITION FOR <d (d="" (i)="" (n="<5000" 100="" 500="" :="" <="" activity:="" and="" as="" cm²="" direct="" dpm="" fixed="" follows:="" measured="" r="" removable="" removable<="" td="" zo="" α="" βγ=""><td></td><td></td><td></td><td></td></d>				
			المراج في وزولا وأدوا	CAR SEA
ADDITIONAL REPORTS COMPLETED Log No.			Log No.	
Skin Contamination Survey Offsit Personnel Effects Contamination Report Routin	e Radioactive Shipm e Radioactive Shipm ne Radioactive Shipe le Counter Log	ent		

			· · · · · · · · · · · · · · · · · · ·	Dat	e		Т	ime .			s	urvey N	lumber			E.C		
			tinghouse ford Company	. ,	10	10/9	ı¥ Fı	rom <u>0730</u>	То	1530	<u>(:</u>)	436 Y	N <u>B</u> o	1 <i>7</i> 9	4.97A	R	Page (of Z
				В	ldg.				Area	Area Room monage of the later of the same of the s						க புழ்ப்சை, ப்	<u>ខ្មាំ រកពេទ្ធ</u>	
	R	ADIATION SU	JRVEY REPORT						300									
Desc	riptio	n of Job							RWP No. R-045 Location NORTH OF 304									
		COUERAC	E OF W. W. MOE	Dic	<u> </u>	TR	<u>56√−</u> c	HET	Check if appropriate. When checked, do not place unrelated information on this record									record.
									Personnel Contamination High Radiation Level Work									
									1 2	CAM/R					_	_	urvey"	
		₩C-1	P-0718 GenceDu	ne 3.1,1	Q.e	u d				Establis					e e es es es <u>e e</u>	Property R		
		05 HC-1	(- 6)10			· E			<u></u>	Radiatio	on/Co	ntamine	ition in	cident		AMINATION		
ltem	P Description of Work Performed, Radiation Deflection Dist. C.F. beta (non					RATE		utron		Direct			mear 100 cm²	2				
No.	Ř (1)	Controls,	and Measurements		W/C	Digt.	0., .	beta (non pen) mrad/h	,	na (pen) iR/hr		rem/hr	t	eta	alpha	beta (d/m)	alpha (d/m)	mrad/hr
ļ	-	~					/							۲ <u>D</u>	۷D			
1		DIRT	1											. >	40	۵۰	<u>ر</u> ک	
2		EQUIPMENT	1 1000										_	۷۵	۵۲	र हैं हैं	OTTE ACE	MARGAID
3		BACKHOE					\overline{Z}							< D	۷۵			
14	-	PERSONNEL		#=													*****	
ļ	-						\leq											†
							-						_					
<u> </u>							//				-		-					
					1			,	i			· -						<u> </u>
ļ 1. k	neck	for personnel dose	rate Continued on s	supplement	al repor	t forn	١.						1					
Inetr	imen Ised	(s) CP /	G-M/Pancake	PAM	[[]	1		Respiratory Protection Worn									
Seri	al No.	(s)	1755 803 2	899					/		/		1 (Supp	lied Air			j
				TED PERSO	NNEL (OOSE	RATES	1 S					٦.	_		10003	Juin "	\$
	P	hase of Work	Based on Measure	ment(s)		Avera	ge Dos	e Rate		Limit App	lying			Filter	` J	age of the second	A COURT	มอกเฉล
			1						WBP	S	1 -	E	Other					
		A 4	PA		2/4				WBP	s		E	7 (Nonepagain and a start year of				
									WBP S E C. W. WILEMAN AND AND AND AND AND AND AND AND AND A									
RPT	Expo	sure	7	,	Vork Lo	ocatio	n Code		L	<u> </u>		Sign		~ · · ·				
			Ø		, .								No Ca			83)	. o''	
	you ir No		WP requirements for this	work?	Did you	atten		i-job meeting N/A No				Rev	iewed l	Зу	(g. 23	a 13	, 3 Date	

RADIATION SURVEY REPOR	RT (cont.)	Survey Number Nº 179437	F.C. Page Z of Z
Further Descriptions, Data, and Comment			
- 110	CONTAMINATION DETE	CTED BURING	MEGT PHIDDIG
<u> </u>		· · · · · · · · · · · · · · · · · · ·	
DIAGRAMS OR SKETCHES			
			į
INSTRUMENTATION			
The α correction factor for the PAM is 7. The β correction factor for the EGM/P-11 is 10.			
DEFINITION FOR AD AS FOLLOWS:			
REMOVABLE ACTIVITY:			
<d 100="" <1000="" =="" cm²="" dpm="" βγ<br=""><d 100="" 20="" <="" cm²="" dpm="" p="" σ<=""></d></d>			
DIRECT MEASURED ACTIVITY:			
$\Omega=35000~\mathrm{dpm}/100~\mathrm{cm}^2~\mathrm{f}$, fixed and removable $\Omega=4.500~\mathrm{dpm}/100~\mathrm{cm}^2~\alpha$ fixed and removable			,
			Intomation to
HPT INITIALS (C)			His prome
ADDITIONAL REPORTS COMPLETED			I - w A lio
 	og No.		Log No.
Rediological Problem Report	Onsite	Radioactive Shipment	
Skin Contamination Survey	Offsite	e Radioactive Shipment	
Personnel Effects Contamination Report	Routir	ne Radioactive Shipment	
Radiation Survey Report		le Counter Log	
nadiation outrey report	Consp		

	Was Was	etinahousa		Date		Т	Time			Survey	y Numi	ber		F.C.		
	Har	stinghouse nford Company		10	141/	94 F	rom <u>073</u> 0	<u> </u>	, 1530		Nº	<u>º 179</u>	1461	R	Page \	of Z
	. 5. 4 7. 6 1. 6	LIDI (EV. DEDAD)	_	Bldg.				Area				Room		-		
R#	ADIATION SI	URVEY REPOR							300							
Description	n of Job							RWP 1	RWP No. 2-045 Location North of 304							
	COUFRAC	oc for w	Mae Mae	<u> </u>	ې ږد	11-29		_ Che	Check if appropriate. When checked, do not place unrelated information on this record							
	TREMCHE	S AND	PLACIN	25 A	SPH	ALT		_	Personnel Contamination High Radiation Level Work							
	IN DRUMS								CAM/Radiation Alarm "Special Survey"							
	WHC- IP-0718 PROCEDURE 3.1. REV &								Establish Dose Rates Property Release Radiation/Contamination Incident RAM Shipment							
Р	P Meter								SE RATE				CONT	AMINATION		
Item E No. R		Work Performed, Radia , and Measurements	<u> </u>	Deflection	Dist. O. Deta (non			1 -	mma (pen) mR/hr	neutror mrem/h			t (dpm)		mear 100 cm ²	1
(1)				vio Wid	3	+ -	peni mradi	-		7711011171	<u>"</u>	beta < D	alpha 	beta (d/m)	alpha (d/m)	mrad/hr
	TREMOCHES													ļ		
2	DIRT				-	\vdash						40	43	62		
3	TOOLS & E	QUIPMENT					1					<u> </u>		2.0	<u> </u>	
	PERSONNE	<u>C.</u>			-	\mathbb{Z}	†					<u> </u>	40	 -		
5	DRUMS FI	LLED		0.1 -		K	,——				_	∡D	12	4.5	40	
	wolk ART	<u>-A</u>			1	7	<u> </u>					ن∓ ∡	42			ļ
! 						$\not\leftarrow$								<u> </u>		
						\angle				İ			<u></u>	1		<u> </u>
1	for personnel dose	a rate Continued	on suppler	mental rep	port for	rm.										
Used	(a) [2] CP	G-M/Pancake	PAM								_		Respira	tory Protection	on Worn	
Serial No.	(s) (209	1755 803	2475	T		/		1		/		☐ supp	plied Air			
			MATED PE	RSONNE	Los	E RATES	S					Filter	_		E Back or Constitution	,
Pt	nase of Work	Based on Meas	surement(s)	Average Dose Rate				Limit App	lying		_		rice W	(Like)	
	$\overline{}$								S	E		U Othe	ar			
	A	$\neg \neg \neg \sim /$	A	1/4				WBP	S	£		None	е			
								WBP	s s	E		<u>). W. W</u>	/ILDMAN	Y		
RPT Expo	sure	e)		Work	Locati	ion Code	3			1	igned	· X() (
	,					e-iob meeting	ı for this	work?		R No.			5837	Date		
4						l n/a			["		·· =•					

RADIATION SURVEY REPORT (cont.)	Survey Number	º 179461	F.C.	Page Z	of 2
Further Descriptions, Data, and Comment			<u></u>	<u> </u>	
- DRUMED UP (11) 55 GAL BAI	PRELS WIT	TH ASPHA	cT.		
- NO CONTANIDATION DETECTE	ED IN TR	Emoch wo	LK		
- DRUMS MOVED TO RMA	NORTH OF	303 K			
					
					·
DIAGRAMS OR SKETCHES					
INSTRUMENTATION The α correction factor for the PAM is 7 The β correction factor for the EGM/P 11 is 16 DEFINITION FOR (D AS FOLLOWS: REMOVABLE ACTIVITY:					
HPT INITIALS			1161 M		ž
ADDITIONAL REPORTS COMPLETED	· · · · · · · · · · · · · · · · · · ·		1101		
Log No.			Log No.		
Radiological Problem Report	Onsite Radioactive Shi	pment			
Skin Contamination Survey	Offsite Radioactive Shi	pment		-	
Personnel Effects Contamination Report	Routine Radioactive Sh	ipment			
Radiation Survey Report	Sample Counter Log			 -	

Attachment 7

i i i at .

Unit Managers Meeting 303-K STORAGE FACILITY FEDERAL BUILDING, RM 784-A Richland, Washington

Meeting Held November 22, 1994 From 10:00 am to 11:30 am

Via video teleconference

TITLE - Ecology Guidance on concrete sampling

SAMPLING FOR ORGANICS IN CONCRETE ECOLOGY GUIDANCE OF NOVEMBER 2, 1994

On November 2, 1994, Ecology (S. E. McKinney) provided the following guidance via cc-mail:

The number of concrete core organic samples can be reduced. The rational for this is that the data from other sites indicates that volatile organics are not remaining in concrete, and therefore, it is unlikely that volatile organics will be found at the 304 Concretion Facility.

The concrete core organic samples will be collected from the following locations: the 4 authoritative floor sampling locations, 1 random floor sampling location, and 1 random outside storage pad sampling location.

If significant levels of volatile organics are found in either the pad or the floor, then the sampling scheme and closure strategy for the floor and/or pad will be re-assessed.

Attachment 8

and the second second

Unit Managers Meeting 303-K STORAGE FACILITY FEDERAL BUILDING, RM 784-A Richland, Washington

Meeting Held November 22, 1994 From 10:00 am to 11:30 am

Via video teleconference

TITLE - Ecology Comments of October 13, 1994, with responses.

304 FACILITY SAMPLING AND ANALYSIS PLAN ECOLOGY COMMENTS OF OCTOBER 13, 1994

1. ECOLOGY COMMENT, SAP Rev. 0, page 1, line 9: The text says that the plan "...provides guidance..." While the SAP is intended to be flexible, it needs to convey to the public that this is the plan to be followed. A stronger term than guidance is needed.

WHC RESPONSE: The text has been changed from "... provides guidance for..." to "...describes..."

2. ECOLOGY COMMENT, SAP Rev. 0, page 1, line 10: The text discusses a RCRA clean closure. This implies that the federal regulations have jurisdiction. This needs to be changed to indicate that Washington state regulations have jurisdiction.

WHC RESPONSE: The text has been changed from referencing RCRA to referencing WAC 173-303.

3. ECOLOGY COMMENT, SAP Rev. 0, page 19, line 3: Section header "6.1.1 Duplicate Samples" needs to be moved to the location between paragraphs.

WHC RESPONSE: The text has been changed.

4. ECOLOGY COMMENT, SAP Rev. 0, page 23, line 45: Has Ecology seen the WHC document Preparation of Concrete for Volatile Organic Analysis (LA-523-435)?

WHC RESPONSE: The document has not yet been transmitted to Ecology. It is being prepared in as part of the closure activities for the 300 Area Solvent Evaporator (Ecology Unit Manager is R. E. Cordts). As additional testing was needed to address internal concerns about the limitations of the procedure have delayed official transmittal to Ecology. Currently, a letter is being prepared for transmittal to Ecology that will address the procedure and the limitations associated with using the procedure. Completion is expected for some time in November.

5. ECOLOGY COMMENT, SAP Rev. 0, page 23, line 15: Why were perchloroethylene and ethyl acetate not included in the SAP?

WHC RESPONSE: Perchloroethylene and tetrachloroethylene are different names for the same chemical substance, $Cl^2C=CCl^2$, (Chemical Abstract Service (CAS) Number 127-18-4). At the DQO meeting of 5/31/94 to 6/1/94, it was agreed to drop perchloroethylene and to keep tetrachloroethylene.

At the DQO meeting of 5/31/94 to 6/1/94, the group failed to identify that ethyl acetate was a "U" listed waste (discarded chemical product). Ethyl acetate has been added back to the SAP.

6. ECOLOGY COMMENT, SAP Rev. 0, page 25, lines 15 to 30: This is a list of data validation package elements. Is the raw data going to be provided with the package? Are there two packages, one with and one without the raw data?

WHC RESPONSE: There will be one data validation package that includes the elements listed above and the raw data.

Attachment 9

The second second

Unit Managers Meeting 303-K STORAGE FACILITY FEDERAL BUILDING, RM 784-A Richland, Washington

Meeting Held November 22, 1994 From 10:00 am to 11:30 am

Via video teleconference

TITLE - Phase I Sampling and Analysis Plan for the 304 Concretion Facility Closure Activities

WHC-SD-EN-AP-177 Revision 1

Phase I Sampling and Analysis Plan for the 304 Concretion Facility Closure Activities

Prepared for the U.S. Department of Energy Office of Environmental Restoration and Waste Management



Hanford Operations and Engineering Contractor for the U.S. Department of Energy under Contract DE-AC06-87RL10930

ENGINEERING CHANGE NOTICE

Page	1	of		2
			_	

 1. ECN	604151
Proj.	

1

(mark one) Supplemental [] Direct Revision [X] Change ECN [] Temporary [] Standby [] Supersedure [] Cancel/Void []	5. Project Title/N		7510			4. Date	
Direct Revision [X] Change ECN [] Temporary [] Standby [] Supersedure [] Cancel/Void []			J. G. Adler, 88210, H6-23, 376-7513			11/18/94	
Change ECN [] Temporary [] Standby [] Supersedure [] Cancel/Void []	304 Concr	ic./Work Order No.	6. Bldg./Sys.	/Fac. No.	7. Approval Designator		
Supersedure [] Cancel/Void []		304 Concretion Facility		304 Concretion Facility		E	
	8. Document Numbers Changed by this ECN (includes sheet no. and rev.)		9. Related ECN No(s).		10. Related PO No.		
	WHC-SD-EN-	-AP-177, Rev. O	n/	a	n/	'a	
11a. Modification Work	11b. Work Package No.		c Complete	tion (Tem	d. Restored to Original Condi- on (Temp. or Standby ECN only)		
[] Yes (fill out Blk.	n/a	n/a	-	n/a			
[X] No (NA Blks. 11b, 11c, 11d)	X] No (NA Blks. 11b, Cog. Engineer Signature		ature & Date Cog. Er		ngineer Signatu	re & Date	
	teria Change [] Design Improvemen	[]	Environme	ntal	[]	
(mark one) As-Found [] Faci	ilitate Const. [ntal ror/Omission	[]	
(mark one) As-found [] Faci 13b. Justification Details	ilitate Const. [Const. Error/Omis	sion []	Design Er			
(mark one) As-found [] Faci 13b. Justification Details 14. Distribution (include	name, MSIN, and no.	Const. Error/Omis	sion []	Design Er		[]	
(mark one) As-found [] Faci 13b. Justification Details 14. Distribution (include 7. G. Adler H F. A. Ruck H	name, MSIN, and no. 16-23 (1) 16-23 (1)	Const. Error/Omis	sion []	Design Er	ror/Omission	[]	
(mark one) As-Found [] Faci 13b. Justification Details 14. Distribution (include 15. G. Adler H F. A. Ruck H J. L. Wright H	name, MSIN, and no.	Const. Error/Omis	sion []	Design Er	ror/Omission RELEASE STAN	[]	

A-7900-013-2 (06/94) GEF095

. 98% juse no. From bg. ENGINEERING CHANGE NOTICE 604151 Page 2 of 2 17, Schedule impact (days) 16. Cost Impact 15. Design Verification CONSTRUCTION ENGINEER ING Required Additional Improvement \$ Π Additional \$ [] Yes Savings Delay Savings [X] No Indicate the related documents (other than the engineering documents identified on Side 1) 18. Change Impact Review: that will be affected by the change described in Block 12. Enter the affected document number in Block 19. Seismic/Stress Analysis Tank Calibration Manual SDD/DD [] \square Health Physics Procedure Stress/Design Report Functional Design Criteria []Interface Control Drawing Spares Multiple Unit Listing ٢٦ Operating Specification Test Procedures/Specification Calibration Procedure []Criticality Specification Installation Procedure Component Index Conceptual Design Report ASME Coded Item Maintenance Procedure Faulament Spec. **Human Factor Consideration** Engineering Procedure Const. Spec. Computer Software Operating Instruction Procurement Spec. Operating Procedure Electric Circuit Schedule Vendor Information ICRS Procedure Operational Safety Requirement OM Manual Process Control Manual/Plan IEFD Drawing FSAR/SAR Process Flow Chart Cell Arrangement Drawing Safety Equipment List Essential Material Specification Purchase Requisition Radiation Work Permit Tickler File Fac. Proc. Samp. Schedule **Environmental Impact Statement** Inspection Plan **Environmental Report** Inventory Adjustment Request **Environmental Permit** 19. Other Affected Documents: (NOTE: Documents listed below will not be revised by this ECN.) Signatures below indicate that the signing organization has been notified of other affected documents listed below. Document Number/Revision Document Number Revision Document Number/Revision 20. Approvals Signature Date Signature Date ARCHITECT-ENGINEER OPERATIONS AND ENGINEERING Cog. Eng. J. G. Adler & PΕ Cog. Mgr. F. A. Ruck III Safety Design Safety Environ. F. A. Ruck III FRAME Environ. Other J. L. Wright JLW 19 W via phone 11/21/4-1 I. L. Metcalf I.L. Metalt un phun 11/19/94

11/22/44

4/22/44

DEPARTMENT OF ENERGY

ADDITIONAL

Signature or a Control Number that

tracks the Approval Signature

K. J. Young 17 Young vie phone

M. S. Hendrix M.S. Hendrix

RELEASE AUTHORIZATION

Document Number:

WHC-SD-EN-AP-177, Rev. 1

Document Title:

PHASE I SAMPLING AND ANALYSIS FOR THE 304 CONCRETION

FACILITY CLOSURE ACTIVITY

Release Date:

11/21/94

This document was reviewed following the procedures described in WHC-CM-3-4 and is:

APPROVED FOR PUBLIC RELEASE

WHC Information Release Administration Specialist:

V. X. Bukland

11/21/93

V.L. Birkland

TRADEMARK DISCLAIMER. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof or its contractors or subcontractors.

This report has been reproduced from the best available copy. Available in paper copy and microfiche. Printed in the United States of America. Available to the U.S. Department of Energy and its contractors from:

U.S. Department of Energy

Office of Scientific and Technical Information (OSTI)

P.O. Box 62

Oak Ridge, TN 37831 Telephone: (615) 576-8401

Available to the public from:

U.S. Department of Commerce

National Technical Information Service (NTIS)

5285 Port Royal Road Springfield, VA 22161 Telephone: (703) 487-4650

1. Total Pages 32 SUPPORTING DOCUMENT 4. Rev No. 3. Number 2. Title WHC-SD-EN-AP-177 1 PHASE I SAMPLING AND ANALYSIS PLAN FOR THE 304 CONCRETION FACILITY CLOSURE ACTIVITIES 6. Author 5. Key Words Name: J. G. Adler 304 Concretion Facility closure activities 11/11/94 analysis sampling quality control Organization/Charge Code - 88210 data validation TCPN: K345C concrete sampling

7. Abstract

This is the sample and analysis plan for the closure activities at the 304 Concretion Facility. This document supports the 304 Concretion Facility Closure Plan, DOE/RL-90-03. The sampling and analysis plan identifies the sample locations, any special handling requirements, quality control samples, required chemical analysis, and data validation need to meet the requirements of the 304 Concretion Facility Closure Plan.

OFFICIAL RELEASE 21
BY WHO
DATE NOV 221994
Sta, 21

RECORD OF REVISION

(1) Document Number
WHC-SD-EN-AP-177

Page 1

(2) Title

PHASE I SAMPLING AND ANALYSIS PLAN FOR THE 304 CONCRETION FACILITY CLOSURE ACTIVITIES

	CHANGE CONTROL RECORD		
(7) nt.t.	(4) Description of Change - Replace, Add, and Delete Pages	Authori	zed for Release
(3) Revision	(4) Description of change * Reptace, Add, and Detete Pages	(5) Cog. Engr.	(6) Cog. Mgr. Date
0	(7) Initial issue, EDT # 603650, Sep. 14, 1994.	n/a	n/a
1	Correction of typographical errors and incorporation of Wash. State Dept. of Ecology comments. ECN 604151.	J.G. Adler	F.A. Ruck III
RS	Ecology comments. ECN 604151.	0 17/7/7	11/18/94
		-	
		1	

WHC-SD-EN-AP-177, Rev. 1

1 2		CONTENTS
1 2 3 4	1.0	PURPOSE
5 6	2.0	OBJECTIVE
7 8	3.0	SITE DESCRIPTION/BACKGROUND
9	4.0	SCOPE OF WORK
l 1 l 2	5.0	SAMPLING AND FIELD ACTIVITIES
13 14	6.0	QUALITY CONTROL SAMPLES
5 6	7.0	LABORATORY ANALYSIS
17 18	8.0	DATA VALIDATION
9 20 21	9.0	REFERENCES
22 23	ATTA	CHMENT
24 25 26	1	Metric Conversion Chart
7 28 29		FIGURES
30	1	Plan View of 304 Concretion Facility Surrounding Area
2	2	304 Concretion Facility, Authoritative Concrete Core and Soil Sample Locations in Areas of Potential Contamination
4	3	304 Concretion Facility, Building Floor Concrete Core Sampling
6	4	304 Concretion Facility, Outside Storage Pad Concrete and Asphalt
8	5	304 Concretion Facility, Changeroom Floor Concrete Chip Sample
Ó	6	Location
1	7	304 Concretion Facility, South Wall Wipe Sample Locations 11
2	8	304 Concretion Facility, East Wall Wipe Sample Locations
3	9	304 Concretion Facility, West Wall Wipe Sample Locations
4 5	10	Wipe Sampling Technique
6 7		TABLES
8 9		-
0	1 2	Summary of 304 Concretion Facility Sampling
2	L	Quality Control Samples

2 3 4 5 6 7

PHASE I SAMPLING AND ANALYSIS PLAN FOR THE 304 CONCRETION FACILITY CLOSURE ACTIVITIES

1.0 PURPOSE

 This document describes the initial (Phase I) sampling and analysis activities associated with the proposed clean closure of the 304 Concretion Facility under the Washington Administrative Code (WAC) 173-303-610, "Dangerous Waste Regulations". This is a supplement to 304 Concretion Facility Closure Plan (DOE-RL 1993a), and should be used in conjunction with the Environmental Investigations and Site Characterization Manual (WHC 1988) for specific procedures.

The strategy for clean closure of the 304 Concretion Facility is to decontaminate, sample (Phase I sampling), and evaluate results. If the evaluation indicates that a limited area requires additional decontamination for clean closure, the limited area will be decontaminated, resampled (Phase II sampling), and the result evaluated. If the evaluation indicates that the constituents of concern are below action levels, the facility will be clean closed. Or, if the evaluation indicates that the constituents of concern are present above action levels, the condition of the facility will be evaluated and appropriate action taken.

The action levels are defined as the concentrations of dangerous waste constituents above the Hanford Site background concentrations identified in Hanford Site Background: Part 1, Soil Background for Nonradioactive Analytes (DOE-RL 1993b) and above the residential concentrations identified in Model Toxics Control Act [WAC 173-340] residential levels.

The criteria used to develop the sample locations, analytical methods, quality control methodology, and data validation methodology were based on the contents of Revision 2 of the 304 Concretion Facility Closure Plan (DOE-RL 1993a) and further developed during the Data Quality Objectives Meetings held on May 30, June 1, and August 25, 1994, and in the monthly Unit Manager Meetings held during 1994.

2.0 OBJECTIVE

The objective is to facilitate a RCRA clean closure of the site by verifying that decontamination has reduced the concentrations of all constituents of concern to below action levels. This objective will be met by collecting samples from 37 locations. The samples will then be analyzed to determine the levels of the constituents of concern.

1 2

3

19

20

21

22

27 28 29

30 31

32 33

43

38

44 45 46

47 48

49

3.0 SITE DESCRIPTION/BACKGROUND

The 304 Concretion Facility is located in the northwest corner of the 300 Area. The layout of the facility is shown in Figures 1 and 2. The facility consists of a building, an associated changeroom, and an external storage area. The building is a steel framed building with sheet metal sides and a poured concrete floor. There is no interior insulation or wallboard. The ceiling of the facility consists of exposed steel trusses (girders). The floor area has a drainage trench, a floor drain, and a sump area. The changeroom is metal with a concrete floor and the interior walls and ceiling are covered with wallboard and insulated. The storage area consists of a concrete pad surrounded by asphalt. The building is also surrounded by an asphalt strip.

The 304 Concretion Facility has performed a variety of functions. From construction in 1952 until the mid-1960's, the facility housed the pilot plants associated with cladding uranium cores. From the mid-1960's until 1971, the facility was used to store engineering equipment and product chemicals. From 1972 until 1994, the facility was used to treat low-level radioactive mixed waste, recyclable scrap uranium generated during nuclear fuel fabrication processes or development activities, and uranium-titanium alloy chips and fines. Also, the facility was used for the repackaging of spent halogenated solvents from the nuclear fuels manufacturing process.

4.0 SCOPE OF WORK

There are a total of 37 sampling locations comprising 12 concrete core. 1 concrete chip, 9 soil, 11 wipe, and 4 asphalt core sampling locations. For the 9 soil sampling locations, samples will be collected at the 0 to 6-inch, 6 to 18-inch, and 18 to 24-inch intervals. Table 1 presents a summary of the 304 Facility sampling.


Analysis for inorganics and volatile organics will be performed on the concrete core and soil samples. Separate concrete core samples will be required for the inorganic and volatile organic analysis (VOA). Analysis for inorganics only will be performed on the concrete chip, wipe, and asphalt samples.

5.0 SAMPLING AND FIELD ACTIVITIES

This section discusses the Phase I sampling of the 304 Concretion Facility. Table 1 presents a summary of the sample types and locations.

Figure 1. Plan View of 304 Concretion Facility Surrounding Area.

1



Figure

2

304 Concretion Facility, Sample Locations in Areas

Authoritative Concrete Core of Potential Contamination.

and Soil

Number of sample locations	Sample types	Inorganic sample	Organic sample	Total number of sample:
	FLOOR	··•		•
4	Authoritative Concrete Core	1	1	8
6	Random Concrete Core	1	0	6
1	Random Concrete Core	1	1	2
4	Soil, 0 to 6 inches	1	1	8
	6 to 18 inches	1	1	8
	18 to 24 inches	1	1	8
(Note: Soil sa	mples and Authoritative Concrete Core Samples			
,	STORAGE PAI	, 1	0	1
l	Random Asphalt Core	i 1	0	1
1	Random Concrete Core	1	1	2
2	Soil, 0 to 6 inches 6 to 18 inches	1 1	1	4
	18 to 24 inches	1	i	4
	CHANGEROOM FL	OOR	-	•
1	Random Concrete Chip	1	0	1
	NORTH WALL			
2	Random Wipe	1	0	2
	SOUTH WALL			
2	Random Wipe	1	0	2
	EAST WALL			
3	Random Wipe	1	0	3
 	WEST WALL			
3	Random Wipe	1	0	2
<u>3</u>		1	U	3
1	GIRDER	1	^	•
1	Wipe	I EVER TO T	0	1
•	WEST-SIDE, BUILDING	EXIEKTOR	_	_
2	Asphalt Core	1	0	2
2	Soil, 0 to 6 inches	1	1	4
	6 to 18 inches 18 to 24 inches	1	1 1	4 4
(Note: Soil sa	mples and Asphalt Core Samples are co-located.	.)	1	*
	EAST-SIDE, BUILDING			
1	Asphalt Core	1	0	1
1	Soil, 0 to 6 inches	1	1	
-	6 to 18 inches	î	î	2 2 2
	18 to 24 inches	1	1	2
(Note: Soil sa	mples and Asphalt Core Samples are co-located.	.)		

5.1 GENERAL PROCEDURES

The activities associated with implementing this SAP will be conducted in accordance with the following environmental investigations instruction (EII) procedures (WHC 1988):

- EII 1.1, Hazardous Waste Site Entry Requirements
- EII 1.5, Field Logbooks
- EII 1.13, Environmental Readiness Review
- EII 5.1, Chain of Custody
- EII 5.2, Soil and Sediment Sampling
- EII 5.4, Field Cleaning and/or Decontamination of Equipment
- EII 5.5, 1706 KE Laboratory Decontamination of RCRA/Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA) Sampling Equipment
- EII 5.10, Obtaining Sample Identification Numbers and Accessing Hanford Environmental Information System Data
- EII 5.11, Sample Packaging and Shipping
- EII 14.1, Analytical Laboratory Data Management.

5.1.1 Total Activity Samples

In addition to the samples listed in Sections 5.2 to 5.6, total activity samples are needed to determine radiological dose rates that control the transportation and handling requirements for the samples. Total activity samples will be collected as determined by the Sampling Field Team Leader as needed to support sampling transportation and handling. If a total activity sample is required for a VOA sample, the original VOA sample will not be used

5.1.2 Figures

Figures 3 through 9 identify the sampling locations at the 304 Concretion Facility. Sampling methodology and selection of the sampling locations is discussed in the 304 Concretion Facility Closure Plan (DOE-RL 1993a). Each sampling area (wall or floor) was divided by a 1 meter by 1 meter grid. Random sampling grid locations were then selected from within each area.

and a separate sample will be collected for total activity analysis.

Figure 3. 304 Concretion Facility, Building Floor Concrete Core Sampling Locations.




Figure 4. 304 Concretion Facility, Outside Storage Pad Concrete and Asphalt Core Sampling Locations.




Figure 5. 304 Concretion Facility, Changeroom Floor Concrete Chip Sample Location.




Figure 6. 304 Concretion Facility, North Wall Wipe Sample Locations.







Figure 7. 304 Concretion Facility, South Wall Wipe Sample Locations.







5.2 CONCRETE CORE SAMPLING

Concrete core samples will be collected at a total of 12 locations. Samples for inorganics analysis will be collected at all 12 locations with VOA samples being collected at only 6 of the 12 locations. The sampling locations for concrete core samples are shown in Figures 2, 3, and 4. Concrete core organic and inorganic samples will be collected from the following locations:

- In the sump (Figure 2)
- In the trench (Figure 2)
- On top of the crack near the south wall (Figure 2)
- Next to the floor drain (Figure 2)
- From the building floor sampling grid 11 south by 4 west (Figure 3)
- From the outside storage pad sampling grid 4 south by 6 west (Figure 4).

The remainder of the samples are concrete core inorganic samples that will be collected from the building floor sampling grid locations shown in Figure 3.

The recommended core size is 4 inches. Other core sizes may be used to meet sampling conditions. The cores will be taken from the center area of each sampling grid. Separate cores will be collected for inorganics analysis and VOA. The cores will be taken in a manner that minimizes any overlap with other core samples.

The appropriate containers and lids (i.e., compatible) will be used for the concrete core VOA samples. Sealable plastic bags may also be used if the concrete cores cannot fit into a jar-type container. The type of container used will be recorded in the field logbook.

There is no SW-846 method for collecting samples from concrete. The sampling method or technique used will be identified and recorded in the field logbook. The water used in coring will be vacuumed and containerized to minimize cross-contamination and displacement of volatiles.

5.3 CONCRETE CHIP SAMPLING

Concrete chip samples will be collected at one location for inorganics analysis. The sampling location for the concrete chip sample is shown in Figure 5. The chips will be collected from the center of the sampling grid to a depth of approximately 3/8 inch. The appropriate containers and lids (i.e., compatible) will be used for the concrete chip samples.

There is no SW-846 method for collecting chip samples from concrete. The sampling method or technique used will be identified and recorded in the field logbook.

5.4 SOIL SAMPLING

Soil samples will be collected at a total of nine locations for VOA and inorganics analysis. Four of the samples are co-located with the authoritative concrete core samples taken from the floor of the facility, as shown in Figure 2. Two of the soil sample locations are located on the storage pad, as shown in Figure 2, with one each being taken by coring through the concrete at the north and south expansion joints. The remaining three soil samples are co-located with the asphalt samples from the east and west sides of the building (Section 5.6). The appropriate containers and lids (i.e., compatible) will be used for the soil VOA samples.

Most of the samples will be collected through the holes that result from the concrete and asphalt coring operations. The concrete sampling is expected to leave several holes in the concrete. A hole or holes specifically for soil sampling will need to be drilled through the concrete at the expansion joints shown in Figure 2. The Sampling Field Team Leader will determine the number of holes that need to be drilled to collect the soil samples at the expansion joints.

When possible, a different concrete core hole will be used for each level and type (VOA or inorganic) of soil sample. The samples will be collected at intervals of 0 to 6 inches, 6 to 18 inches, and 18 to 24 inches. At each interval, one VOA sample and one inorganic analysis sample will be collected. Hand tools will be used to collect the soil samples.

5.4.1 Additional Requirements for the Collection of VOA Soil Samples

No deviations are permitted from the requirements of this section. The VOA soil samples will be collected as soon as possible after the concrete core samples have been collected. Volatile organic analysis soil samples will be collected the same day that the concrete cores are drilled. At any given sampling interval, the VOA soil sample will be collected before the inorganics sample. The VOA samples will be collected so that there is minimum or no headspace in the containers. Mixing or homogenizing of the material comprising the VOA sample is not allowed.

5.5 WIPE SAMPLING

Wipe samples will be collected at a total of 11 locations (10 wall and 1 girder) for inorganics analysis. Figures 6, 7, 8, and 9 show the locations of the 10 wall samples for inorganics analysis. The one girder wipe sample is to be collected from the top of one girder directly above the area where the concretion process was located and where the fire occurred. As viewed from Figure 2, the boundaries of this area are defined as follows:

• north boundary - an east-west line at the floor drain

 east boundary - a north-south line 8 feet east of the building center line

> 7 8 9

- south boundary an east-west line 10 feet from the south wall
- west boundary a north-south line 8 feet west of the building center.

The specific girder will be chosen at the discretion of the Sampling Field Team Leader and identified in the field logbook.

5.5.1 Wipe Sampling Methodology

14

15

16 17

18

19

The general wipe sampling methodology presented in A Compendium of Superfund Field Operations Methods (EPA 1987) will be used. Wipe sampling of surfaces will be performed by wiping a 100-square-centimeter area using Whatman No. 421 filter paper or equivalent. The filter papers will be laboratory-prepared with toxicity characteristic leaching procedure (TCLP) extraction fluid number 2 and containerized in individual glass containers. The TCLP extraction fluid number 2 will be prepared as specified in Section 5.7.2 of SW-846 Method 1311. (Note: The TCLP extraction fluid is only being used as a solvent for wipe sampling. No TCLP analysis will be performed.)

20 21 22

23 24

25 26

27

28

29

The interior walls have been divided into 1-square-meter sample grids (Figures 6, 7, 8, and 9). One filter paper will be used to wipe the wall surface from a 100-square-centimeter section within each sample grid. The entire 100-square-centimeter area within a disposable template will be carefully covered, using vertical strokes, starting at one end and progressing to the other end (Figure 10). The filter paper will be held using clean gloves to prevent contamination. A new pair of gloves will be used for each wipe sample. Care will be taken to wipe the surface only once throughout the sampling effort.

30 31 32

33

The top of the one steel girder chosen for sampling will be wipe sampled using the same technique as described previously. One 100-square-centimeter area will be wipe sampled.

34 35 36

37 38

39

After the area is wiped, the filter paper will be folded with the exposed side in, and then folded over to form a 90-degree angle in the center of the filter. The filter then will be returned to the original glass container. angle first, and immediately sealed.

40 41 42

5.6 ASPHALT CORE SAMPLES

43 44 45

46

47

48 49

50


51

Asphalt core samples will be collected at a total of four locations for inorganics analysis. One asphalt core sample will be collected from a location on the outside storage pad (Figure 4). In addition, two asphalt core samples will be obtained from the west side of the 304 Building and one from the east side. The exact sampling locations will be determined at the time of sampling, and will be taken in places where contamination is most likely to have occurred (e.g., cracks, asphalt joints, visible stains). The specific locations will be chosen at the discretion of the Sampling Field Team Leader

⁵²

¹Whatman No. 42 is a trademark of Whatman, Incorporated.

Figure 10. Wipe Sampling Technique.



and identified in the field logbook. The recommended core size is 4 inches. Other core sizes may be used to meet sampling conditions. The cores will be taken in a manner that minimizes any overlap with other core samples. Sealable plastic bags may also be used if the asphalt cores cannot fit into a jar-type container.

There is no SW-846 method for collecting core samples from asphalt. The sampling method or technique used will be identified and recorded in the field logbook. The water used in coring will be vacuumed and containerized to minimize cross-contamination and displacement of volatiles.

6.0 QUALITY CONTROL SAMPLES

This section identifies the quality control samples for the sampling effort at the 304 Concretion Facility.

6.1 GENERAL INFORMATION

Field quality control samples will be collected by the sampling team and documented in the sampling logbook in accordance with EII 1.5, "Field Logbooks" (WHC 1988). Deionized water will be used for the field and equipment blanks because it provides the excellent sensitivity to contamination. Table 2 presents a summary of the quality control samples for the 304 Concretion Facility. While the number of samples is sufficient to determine if the 304 Facility can be clean-closed, there is not a sufficient number of samples for a detailed statistical analysis.

6.1.1 Duplicate Samples

Duplicate samples are included for each type of sample (concrete core inorganic, concrete core VOA, concrete chip, asphalt core, soil inorganic, soil VOA, and wipe). The purpose of the field duplicate samples is to indicate the precision of sampling and analysis.

Duplicate samples are collected from the same location and using the same methods or techniques as a regular sample, but placed in a separate container.

6.1.2 Equipment Blanks

Equipment blanks are included for each type of sample (concrete core inorganic, concrete core VOA, concrete chip, asphalt core, soil inorganic, soil VOA, and wipe). The purpose of the equipment blanks is to check for sampling device cleanliness from the laboratory decontamination efforts.

The equipment blanks for concrete core, concrete chip, asphalt core, and soil samples are collected using deionized water transported to the sampling site. At the site, the deionized water is poured over or through the sample collection device, collected, and returned for analysis.

2	SAMPLE TYPES	Concrete Core ¹	Concrete Chip	Soil		Wipe ²	Asphal t	
3	NUMBER OF SAMPLE LOCATIONS	12	1	9			11	4
4 5	SAMPLING INTERVALS (depth in inches)	na	na –	0 to 6	6 to 18	18 to 24	na	na
6 7 8	NUMBER OF SAMPLES Inorganic Analysis	12	1	9	9	9	11	4
9	Organic Analysis	6	na	9	9	9	na	na
1 2 3	DUPLICATE SAMPLES Inorganic Analysis	1	1	1	1	1	1	1
4	Organic Analysis	1	na	1	1	1	na	na
6 7 8	EQUIPMENT BLANK ⁴ (Inorganic Analysis)	V 5	na –	V5			1	V 1
9 0 1	CONFIRMATORY WIPE SAMPLE (Inorganic Analysis)	na	na		na		1	na
2	FIELD BLANKS ⁵ (Inorganic Analysis)	V 5	na		V 5		V 1	V 3

26

27

28 29

30 31

32

33

34 35

19

Includes both the 4 authoritative and the 8 random concrete core samples.

Includes both the 10 random wipe samples and the 1 wipe sample from the girder.

Includes both the 1 random asphalt sample and the 3 asphalt core samples.

Frequency for each sample type: 1 per day of sampling and 1 after each time sampling equipment undergoes field decontamination.

⁵Frequency for each sample type: 1 per day of sampling or for each 20 samples collected.

na = not applicable.

- V1 = Number of samples is variable; 1 expected, covering an estimated 1 day of sampling.
- V3 = Number of samples is variable; 3 expected, covering an estimated 3 days of sampling.
- V5 = Number of samples is variable; 5 expected, covering an estimated 5 days of sampling.

The equipment blanks for wipe samples consist of filter paper saturated with TCLP extraction fluid number 2. They remain sealed while in the field and are returned for analysis. Additional details are provided in Section 6.5.

6.1.3 Field Blanks

Field blanks will only be taken if field decontamination procedures are used. The purpose of the field blanks is to check the effectiveness of the field decontamination procedures to determine if there is contamination originating in the sampling environment.

Field blanks for any field decontaminated equipment are collected by pouring deionized water over or through the sampling device. Then the sample is returned for analysis.

Field blanks for the wipe samples will be collected by removing the filter paper (saturated with TCLP extraction fluid number 2) from the container. The filter paper is then exposed to air for the same amount of time required to collect a wipe sample, then returned to the original sample container.

6.1.4 Trip Blanks

Trip blanks will not be included for the VOA samples. The reasons for their exclusion are the following.

- Neither sand nor deionized water is a suitable medium for a trip blank for soil. Sand has little to no affinity for adsorbing volatile organics. Water absorbs organics, whereas soil primarily adsorbs organics; because the mechanism is different, water is not a suitable material for the trip blanks.
- The field and equipment blanks will 'trip' with the routine samples and will contain any volatile contamination that may be present.

6.2 CONCRETE CORE FIELD QUALITY CONTROL SAMPLES

The quality control requirements for concrete core samples are as follows.

- One duplicate concrete core sample will be collected for inorganic analysis. The sample will be collected from the random sample location shown in Figure 3.
- One duplicate concrete core sample will be collected for VOA. The sample will be collected from the random sample location shown in Figure 3.

- One equipment blank (deionized water) will be collected for inorganic analysis per day of sampling.
- If field decontamination procedures are used, one field blank will be collected after decontamination. One field blank (using deionized water) will be collected per day of sampling or for each 20 samples.

The cores will be collected as close to each other as possible.

6.3 CONCRETE CHIP FIELD QUALITY CONTROL SAMPLES

The quality control requirements for concrete chip samples are as follows.

15

- One duplicate concrete chip sample will be collected for inorganic analysis. The sample will be collected from the random sample grid location shown in Figure 5.
- One equipment blank (deionized water) will be collected for inorganic analysis per day of sampling.
- If field decontamination procedures are used, one field blank will be collected after decontamination. One field blank (using deionized water) will be collected per day of sampling.

27

6.4 SOIL FIELD QUALITY CONTROL SAMPLES

The quality control requirements for soil samples are as follows.

- Three duplicate soil samples will be collected for VOA. Duplicate soil samples will collected at 0 to 6-inch, 6 to 18-inch, and 18 to 24-inch intervals. The sample will be collected from the sump sampling location shown in Figure 2. This location was chosen because it has a greater potential for volatile organics contamination.
- Three duplicate soil samples will be collected for inorganic analysis. Duplicate soil samples will collected at 0 to 6-inch, 6 to 18-inch, and 18 to 24-inch intervals. Each duplicate sample will be collected on different sampling days. One of the samples will be collected from the floor drain sampling location shown in Figure 2. The other two samples will be collected from locations determined by the Sampling Field Team Leader and the locations recorded in the field logbook.

• One equipment blank (deionized water) will be collected for inorganic analysis per sampling day.

48 49 50

51

 If field decontamination procedures are used, one field blank will be collected after decontamination. One field blank (using deionized water) will be collected per day of sampling or for each 20 samples.

6.5 WIPE FIELD QUALITY CONTROL SAMPLES

The quality control requirements for wipe samples are as follows.

- One duplicate wipe sample will be collected for inorganic analysis. The duplicate will be collected from a 100-square-centimeter area adjacent to the original sample, i.e. within the 1-square-meter sample grid. The sample will be collected from the random sample grid location shown in Figure 8.
- One equipment blank (clean filter paper saturated with TCLP extraction fluid number 2) will be collected for inorganic analysis. This sample will remain sealed during the sampling event and the filter paper will not be handled in the field.
- One field blank (using clean filter paper saturated with TCLP extraction fluid number 2) will be collected per day of wipe sampling or for each 20 samples. The filter paper will be removed from the container (with the sampler wearing clean gloves) and exposed to air for the same amount of time required to collect a wipe sample.

In addition to the quality control samples listed, one confirmatory wipe sample will be collected. This sample will only be taken once during the sampling of the 304 Concretion Facility. The purpose of this sample is to determine if wipe samples are effective.

• One confirmatory wipe sample will be collected for inorganic analysis. The confirmatory sample will be collected from the same 100-square-centimeter area as the original wipe sample. The sample will be collected from the random sample grid location shown in Figure 9.

6.6 ASPHALT CORE FIELD QUALITY CONTROL SAMPLES

The quality control requirements for asphalt core samples are as follows.

- One duplicate asphalt core sample will be collected for inorganic analysis. The sample will be collected from the same sample location as the asphalt core sample collected on the outside east of the building (Section 5.6).
- One equipment blank (deionized water) will be collected for inorganic analysis per pay of sampling.
- If field decontamination procedures are used, one field blank will be collected after decontamination. One field blank (using deionized water) will be collected per day of sampling or for each 20 samples.

The cores will be collected as close to each other as possible.

7.0 LABORATORY ANALYSIS

Laboratory analysis will be performed on the samples to determine the concentration and, for wipe samples, the amount of the constituents of concern that remain at the 304 Facility after decontamination.

7.1 CONSTITUENTS OF CONCERN

The samples to be analyzed for inorganic constituents are as follows.

- concrete core inorganic samples
- soil inorganic samples
- asphalt samples
- concrete chip samples
- wipe samples.

The inorganic constituents of concern are as follows.

- Beryllium
- Cadmium
- Chromium
- Lead
- Nickel
- · Uranium.

The samples to be analyzed for volatile organic constituents are as follows.

- concrete core organic samples
- soil organic samples.

The volatile organic constituents of concern are as follows.

- Trichloroethylene
- Tetrachloroethylene
- 1,1,1-Trichloroethane
- 1,1-Dichloroethylene
- cis-1,2-Dichloroethylene
- trans-1,2-Dichloroethylene
- Ethyl acetate
- Methyl ethyl ketone.

The analytical methods are identified in Section 7.5.

7.2 SAMPLE PREPARATION FOR CONCRETE CORE, CONCRETE CHIP, AND ASPHALT CORE INORGANIC SAMPLES

Before the concrete core, concrete chip, and asphalt core samples can be analyzed for inorganics, it may be necessary to crush or break-up the samples to reduce the size of the material sent for analysis. Size reduction may

occur in either the field or the laboratory. If size reduction occurs in the field, the sample number, technique used for reduction, and any other pertinent or relevant information, will be documented in the field logbook.

7.3 SAMPLE PREPARATION FOR CONCRETE ORGANIC SAMPLES

The preparation of the concrete organic samples will be performed at the 222-S Analytical Laboratory. Before the concrete cores can be analyzed for volatile organics, additional laboratory preparation is required. Before analysis, the concrete core will be handled according to *Preparation of Concrete for Volatile Organics Analysis*, (WHC 1994). The resulting extractant from each sample will be analyzed at the 222-S Analytical Laboratory for volatile organics in accordance with Section 7.5.

7.4 SAMPLE PREPARATION FOR WIPE SAMPLES

Before the wipe samples can be analyzed for inorganics, additional laboratory preparation is required. Each wipe sample will be handled according to *Acid Digestion of Sediments*, *Sludges*, and *Soils*, SW-846 Method 3050 (EPA 1986). The resulting extractant from each sample will be analyzed for inorganics in accordance with Section 7.5.

7.5 ANALYTICAL METHODS

 The SW-846 analytical methods (EPA 1986) will be used for the sample analysis, except for uranium. The uranium results will be determined by SCINTREX UA-2 laser method, Eastern Environmental Radiation Facility Method 00.07 (EPA 1984) or Laser Kinetic Phosphorimetric Analysis. The inorganics analysis methods are as follows:

 Method 6010, Inductively coupled plasma-atomic emission spectroscopy (analysis will be for the target analyte list. Except for lead, this list includes the inorganic constituents of concern listed in Section 6.1) (This method addresses the following constituents of concern: beryllium, cadmium, chromium, and nickel.)

 Method 7421, Lead (Atomic Absorption, Furnace Technique). (This method addresses the following constituent of concern: lead.)

• SCINTREX UA-2 laser method, EERF Method 00.07, or Laser Kinetic Phosphorimetric Analysis. (This method addresses the following constituent of concern: uranium.)

²SCINTREX is a trademark of SCINTREX, Incorporated.

The VOA methods are as follows:

- Method 8260, Volatile organic compounds by gas chromatograph/mass spectroscopy capillary column technique. (This method addresses the following constituents of concern: trichloroethylene, tetrachloroethylene, 1,1,1-trichloroethane, 1,1-dichloroethylene, cis-1,2-dichloroethylene, trans-1,2-dichloroethylene, and ethyl acetate. Ethyl acetate is not included as a target analyte in the most current revision (Revision 0, July 1992) of Method 8260. However, ethyl acetate can be identified by Method 8260 as a tentatively identified compound. If ethyl acetate is found in an estimated concentration approaching the clean-up level, further sampling and quantitative analysis will be performed if directed by Ecology.)
- Method 8240, Volatile organics by gas chromatography/mass spectrometry. (This method addresses the following constituent of concern: methyl ethyl ketone.)

7.6 DATA REQUIREMENTS FOR THE ANALYTICAL LABORATORIES

The 222-S Laboratory is required to record and provide sufficient data in the performance of any preparation and analysis of the concrete VOA samples to support the data validation described in Section 8.0. The contract laboratory is required to supply stand-alone data packages to support full data validation.

7.7 BATCHING OF INORGANIC SAMPLES

The inorganic samples will be batched for analysis, providing holding times are not violated. The inorganic samples consist of 12 concrete core inorganic, 27 soil inorganic, 11 wipe, 1 concrete chip, and 4 asphalt core samples and the associated quality control samples. The concrete core organic and soil organic samples will not be batched.

8.0 DATA VALIDATION

Data validation will be conducted to Level D as defined in the Data Validation Procedures For Radiological Analysis (WHC 1993a) and Data Validation Procedures For Chemical Analyses (WHC 1993b), as appropriate. Level D validation consists of the following:

- verification of required deliverables
- verification of requested versus reported analyses
- verification of transcription errors

- evaluation and qualification of results based on analytical holding times
- matrix spikes
- laboratory control samples (radiological samples only)
- laboratory duplicates
- analytical method blanks
- chemical recoveries
- tracer recoveries
- surrogate recoveries
- initial and continuing instrument calibrations
- quench monitoring
- counting instrument resolution checks
- calculation checks.

There will be 100 percent validation of the data because of the small size of the sample set and that similar types of samples (e.g., all wipe samples) can be batch analyzed at the analytical laboratory.

9.0 REFERENCES

- Comprehensive Environmental Response, Compensation, and Liability Act of 1980, as amended, 42 USC 9601 et seq.
- DOE-RL, 1993a, 304 Concretion Facility Closure Plan, DOE/RL-90-03, Rev. 0, U.S. Department of Energy, Richland Operations Office, Richland, Washington.
- DOE-RL, 1993b, Hanford Site Background: Part 1, Soil Background for Nonradioactive Analytes, DOE/RL-92-24, Rev. 1, U. S. Department of Energy, Richland Operations Office, Richland, Washington.
- EPA, 1984, Eastern Environmental Radiation Facility Radiochemistry Procedures Manual, 520/5-84/006, U.S. Environmental Protection Agency/Eastern Environmental Radiation Facility, Montgomery, Alabama.
- EPA, 1986, as amended, Test Methods for Evaluating Solid Waste:

 Physical/Chemical Methods, SW-846, 3rd Edition, U.S. Environmental Protection Agency, Washington, D.C.

		•
1 2 3 4	EPA/540/P-87/0	ndium of Superfund Field Operations Methods, DOI, Office of Emergency and Remedial Response, ental Protection Agency, Washington, D.C.
5 6	Resource Conservati	ion and Recovery Act of 1976, 42 USC 6901 et seq.
7 8 9	WAC 173-303, "The E Code, as amend	Dangerous Waste Regulations," Washington Administrative ded.
10 11 12		Model Toxics Control Act Cleanup Regulations," Washington Code, as amended.
13 14 15	WHC, 1988, Environm WHC-CM-7-7, We	mental Investigations and Site Characterization Manual, estinghouse Hanford Company, Richland, Washington.
16 17 18	WHC, 1993a, <i>Data Va</i> WHC-SD-EN-SPA-	alidation Procedures For Radiological Analysis, -001, Westinghouse Hanford Company, Richland, Washington.
19 20 21	WHC, 1993b, Data Va WHC-SD-EN-SPA-	alidation Procedures For Chemical Analysis, -002, Westinghouse Hanford Company, Richland, Washington.
22 23	WHC, 1994, <i>Preparat</i> Westinghouse H	tion of Concrete for Volatile Organics Analysis, LA-523-435 Hanford Company, Richland, Washington.

METRIC CONVERSION CHART

Into metric units

Out of metric units

If you know	Multiply by	To get	If you know	Multiply by	To get	
	Length		Length			
inches	25.40	millimeters	millimeters	0.0393	inches	
inches	2.54	centimeters	centimeters	0.393	inches	
feet	0.3048	meters	meters	3.2808	feet	
yards	0.914	meters	meters	1.09	yards	
miles	1.609	kilometers	kilometers	0.62	miles	
	Area			Area		
square inches	6.4516	square centimeters	square centimeters	0.155	square inches	
square feet	0.092	square meters	square meters	10.7639	square feet	
square yards	0.836	square meters	square meters	1.20	square yards	
square miles	2.59	square kilometers	square kilometers	0.39	square miles	
acres 0.404 hectares		hectares	hectares	2.471	acres	
	Mass (weight)	Mass (weight)			
ounces	28.35	grams	grams	0.0352	ounces	
pounds	0.453	kilograms	kilograms	2.2046	pounds	
short ton	0.907	metric ton	metric ton	1.10	short ton	
	Volume		Volume			
fluid ounces	29.57	milliliters	milliliters	0.03	fluid ounces	
quarts	0.95	liters	liters	1.057	quarts	
gallons	3.79	liters	liters	0.26	gallons	
cubic feet	0.03	cubic meters	cubic meters	35.3147	cubic feet	
cubic yards	0.76	cubic meters	cubic meters	1.308	cubic yards	
	Temperature		Temperature			
Fahrenheit	subtract 32 then multiply by 5/9ths	Celsius	Celsius	multiply by 9/5ths, then add 32	Fahrenheit	

Source: Engineering Unit Conversions, M. R. Lindeburg, PE., Second Ed., 1990, Professional Publications, Inc., Belmont, California.

WHC-SD-EN-AP-177, Rev. 1

DISTRIBUTION

Number of copies				
<u>OFFSITE</u>				
1	U.S. Environmental Protection Agency			
	D. L. Duncan	Seattle HW-106		
3	Washington State Department of Ecol	Ecology		
	S. E. McKinney (2) D. C. Nylander	Lacey N1-05		
<u>ONSITE</u>				
4	U.S. Department of Energy- Richland Operations Office			
	A. B. Joy R. N. Krekel E. M. Mattlin (2)	R3-79 A5-15 A5-15		
17	Westinghouse Hanford Company			
	J. G. Adler M. S. Hendrix I. L. Metcalf D. E. Rasmussen J. A. Remaize C. J. Stephen D. B. Tullis J. L. Wright K. J. Young Central Files (2) EDMC (2) RCRA File/GHL Unclassified Document Control OSTI (2)	H6-23 H4-23 L6-18 N1-47 L6-18 L4-16 N1-80 L6-26 S3-90 L8-04 H6-08 H6-23 A4-65 L8-07		
1	MACTEC			
	J. K. Bartz	R3-82		

Distribution:

J.	G.	Adler	WHC	H6-23
J.	Κ.	Bartz	GSSC	R3-82
R.	Μ.	Carosino	RL	A4-52
D.	L.	Duncan	EPA	Seattle - HW-106
Μ.	N.	Jaraysi	Ecology	B5-18
Α.	В.	Joy	RL	R3-79
Р.	J.	Mackey	WHC	B3-15
Ε.	Μ.	Mattlin	RL	A515
S.	Ε.	McKinney	Ecology	Lacey
Ι.	L.	Metcalf	WHC	L6-26
S.	Μ.	Price	WHC	H6-23
D.	Ε.	Rasmussen	WHC	N1-47
J.	Α.	Remaize	WHC	L6-26
F.	Α.	Ruck III	WHC	H6-23
J.	L.	Waite	WHC	B2-35
RCF	RA F	File/GHL	WHC	H6-23
		File Custodian	WHC	H6-08

ADMINISTRATIVE RECORD: 304 Concretion Facility, TS-3-2, [Care of EDMC, WHC (H6-08)]

Washington State Department of Ecology Nuclear and Mixed Waste, Hanford Files, P.O. Box 47600, Olympia, Washington 98504-7600

Environmental Protection Agency Region 10, Seattle, Washington 98101, Record Center, Mail Stop HW-074

Please send comments on distribution list to Kym D. Tartar (H6-23), (509) 373-4701